


Wakefit Innovation Ltd					
Quality Inspection Report - Page 1/1					
FG QUALITY AQL CHART					
Category : Wakefit ErgoTech EcoLatex Classic Mattress		SKU ID : WMFWLM-SAMPLE-SKU-001	Asin : B0MAT00005	Date : 23 Sep 2026	
Production Qty : 20			Checked Qty : 20	Inspected Date :	Checked Qty : 21
PO No :			PO Qty :	Inspected By : Tilak	PO Qty :
Pass Qty : 20			Rejection Qty : 00	Verified By : Chellappan	Rejection Qty : 01
Qc Inspection Check points					
Check points	Status	Check points	Status	Check points	
Length	Ok	Loose Cover	Ok	Loose Cover	
Width	Ok	Tight Cover	Ok	Tight Cover	
Thickness	Ok	Pen Mark	Ok	Pen Mark	
Stitch Open	Ok	Thread Out issue	Ok	Thread Out issue	
Brand Label Missing	Ok	Zip Damage	Ok	Zip Damage	
Cover Size Issue	Ok	Cover Open	Ok	Cover Open	
SAP Label Missing	Ok	Cover Damage	Ok	Cover Damage	
LDPE/PVC Packing Issue	Ok	Label Damage	Ok	Label Damage	
HDPE Bag Packing Damage	Ok	Label Missmatch	Ok	Label Missmatch	
Mismatch Product	Ok	SAP Label Damage	Ok	SAP Label Damage	
Stains	Ok	Barcode & SAP Label	Ok	Barcode & SAP Label	
AQL Checking Process :					
					
					
Quality Inspection Report - Page 2/2					
AQL CHART 2.5 STD					
Shipment Qty	Sample Size	Major Defect	Major Defect Reject	Major Defect	Major Defect Reject
20	20				
Defect Description			Critical	Major	Critical
Total Defect					
Defect Images :					
Quality : Tilak		Production : Rajesh		Production : Rajesh	