


Category : Gravita HB 3D Amrest NB Sea Green MLSS	SKU : WSCHRGRAVIHB3DNBRWESGSGMLSS	Inspected Date : 10/09/2026
	Verified By : Roshana	Inspected By : Srivanti / Bishnu
Production Qty : 110	Checked Qty : 110	Pass Qty : 105
		Rejection Qty : 05

Qc Inspection Check points

Check points (Backrest)	Status	Check points (Headrest & Assembly)	Status
Bolt broken in insert	Ok	Knitted air mesh - cloth damage	Ok
Inner thread damage	Ok	Knitted Air mesh-Line mark	Ok
Scratches inner	Ok	Hanger scratches	Ok
Black mark	Ok	Hanger Dent mark	Ok
Colour mismatch inner	Ok	HB takia Inner damage	Ok
Insert missing inner	Ok	HB Takiya outer damage	Ok
Bubble mark inner	Ok	HB takia outer pin damage	Ok
Yellow mark inner	Ok	HB takia outer scratch	Ok
Damage inner	Ok	HB takia Mold mark	Ok
C96 mesh cloth damage	Ok	HB takia mechanism damage	Ok
Stain mark - C96 mesh cloth	Ok	Bolt broken in HB takia mechanism	Ok
Outer scratch outer	Ok	Hb takia inner bend	Ok
Outer denut thread issue outer	Ok	HB takia outer bend	Ok
White mark outer	Ok	HB pu foam damage	Ok
Black mark outer	Ok	Bolt broken in Hector takia outer	Ok
Insert missing outer	Ok	Handle lock working	Ok
Dent mark outer	Ok	Handle sagging	Ok
Bend outer	Ok	Mechanism lock working	Ok
Bolt broken in insert outer	Ok	Mechanism recline conduction	Ok
Headrest denut missing outer	Ok	Seat comfort	Ok
Headrest denut thread damage outer	Ok	Chair tilted condition	Ok

Checking images



Defect reason : Cloth needle marks

Quality : Sumanta	Production Assembly line : Shakti	Packaging line : Shubham
-------------------	-----------------------------------	--------------------------