

	Valuatio	n Report for	Indostar Hom	e FInance Pvt 1	Ltd	
<b>Application Details:</b>						
File NO. / LAN No. / SFDC no	DLBAN0HL-04240076971 Dat		Date of Repor	rt	20-04-2024	
Name of Applicant	Mr.YOGESHA	BS	Contact Perso	on name & No.	Mr. Suresh & 9738734701, 8217457194	
Loan Type (HL/LAP/BT)	Self construct	ion	Person met a	t site	Mr. Suresh	
Name of Property Owr	ner as per lega	l document	Mr. Suresh			
Documents provided	Katha Date: 1	9-06-2023	<u>-</u>			
Location Details:	<u> </u>					
			rty No.60/576, 'umkur District		lage, Bili Devalaya Village	
	Locality Name	е	Kunigal	Landmark nearby	Sri Durga Parameshwari Temple	
Address of Property	Distance from	city centre	05 Kms	Lat/Long	13.015865, 76.990234	
	Distance from Office	Indostar	44 Kms		/ _ \	
	Address as per Initiation : Kunigal Tumkur					
					152500400800200061, Bili Faluk, Tumkur District	
Legal Address of the Property: (As per	Floor No. of Property			G+02f		
Title Deed or	Property State		90	Karnataka		
Sanctioned Plan)	Property City		10	Kunigal		
	Property Pincode		572130			
Address Matching (Yes / No)	Yes Jurisdiction / Local Munici		Local Municipa	al body	Village Panchayat	
Property holding type (Freehold / Leasehold)	Freehold		Marketability (Poor / Fair / Good)		Good	
Property Occupied by (Self / Tenant / Vacant / Under Construction)			Under Construction			
Type of the Property (Flat / Independent House / Commercial Building / Commercial Unit / Industrial / Plot)			Residential			
Occupancy Status SOF	RP / SOCP / Re	nted / Vacant		SORP		
Schedule of the Property	As per legal documents		As per site visit			
North	Road		17 Feet Road			
East	Passage then Devaraju		Residential House			
West	Road		20 Feet Road			
South	Property belo	ngs to Vijay Kı	ımar	Vacant Site		

Page No: **1 of 8** Ref No. **KV/2024/04/107569** 



Boundaries matching (Yes / No)	Yes	Property Identified (Yes / No)		NA		
Approach Road Size (<5 ft/5-10 ft/ 10-15 ft/ 15ft)	20 Feet					
	NDMA	PARAMETER	RS			
Nature of Building / Wing	Residential	Plan Aspect Ratio	No	Structure Type (Load Bearing, RCC, Composite Structure, Others)	RCC	
Projected Parts Available	NA	Type of Masonary	NA	Expansion Joints Available	No	
Roof Type	RCC	Steel Grade	Fe-415	Mortar Type	NA	
Concrete Grade	M30	Environment Exposure Condition	Good	Footing Type	Raft	
Sesmic Zone	Zone II	Soil Liquefiable	No	Coastal Regulatory Zone (Yes/No)	No	
Soil Slope Vulnerable to Landslide	Not Vulnerable	Flood Prone Area	No	Ground Slope More than 20%	Not Vulnerable	
	Sanctioned Plan Provided	No				
	Layout plan details : Sanctioned No. / Permit No.	. NA				
	Construction plan details : Sanctioned No. / Permit No.	NA				
	Date of Sanction NA					
Approved plan details	Plan validity NA					
	Approving authority	ring authority NA				
	Approved usage (Residential / Industrial / Commercial / Mixed Usages)	Residential				
	Number of Floors in Building	G+02F				
Technical Details:						
Construction Quality (Good / Fair / Poor)	Under construction		Lift Available (Yes / No) No. of lifts		No 0	
Current Occupant of Property (Owner / Tenant / Vacant)	Under Construction		Separate Independent Access (Yes / No)		No	



Page No: **2 of 8** Ref No. **KV/2024/04/107569** 



Accomm details: and Occ	Floor wise	GF - 02BHK/U	JC, FF - 03X01	BHK/UC, SF - (	)1BHK/UC		
Plot area details		As per docs		As p	er plan	As per sit	te visit
East to west		40			0	40	
North to South		50		0		50	
Land are	ea in (Sq Ft)	2000		0		2000	
BUA Area Details	No. of rooms	No. of kitchens		No. of bathrooms	Sanctioned Usage	Actual Usage	
GF	02	01		01	NA	Residential	
FF	03	01		01	NA	Residential	
SF	01	01		01	NA	Residential	
Items	Permissible area as per plan (Sq Ft)	Land Component (Sq Ft)	Permissible FSI	Permissible construction as per FSI (Sq Ft)	Compoundable construction Area (Sq Ft)	Actual Construction (BUA) (Sq Ft)	FSI violation in %
	3000	2000	1.5	3000	4200	3000	0
	demolition Medium /	Low					
Status of the Property (Plot / Under Construction / Completed / Construction on Hold)		Under Constr	ruction	% completed	50	% Recommended	60
Current age of Property 0		0		Residual Age		60 After completion	
Items		Area details in Sq Ft		Rate Per Sq Ft		Total Value in Rupees	
Land value		2000		Rs.1,000.00		Rs.20,00,000.00	
GF		1040		1800		Rs.18,72,000.00	
FF		1385		1800		Rs.24,93,000.00	
SF 575			1800		Rs.10,35,000.00		
Depreciation 0				Rs.0			
Fair Market value as on date (In Rs.)				Rs.74,00,000.00			
Government Value					0		
Distressed / Forced Value @ 80 %						Rs.59,20,000.00	
Valuation Done Earlier				No			
In Municipal / Development Authority demolition list (Yes / No)				No			
Is property in negative area (Yes / No)					No		
Remark	s If any:					•	

Page No: **3 of 8** Ref No. **KV/2024/04/107569** 



- 1. This report is finalized on the basis of Katha Provided
- 2. Katha Date: 19-08-2023 in favor of Mr. Suresh
- 3. Plot area as per doc and at actual 2000sft (EEW-40ft, NS-50ft), same plot area is considered for valuation.
- 4. Approved Plan not provided at actual G+02F is Under Construction of TBUA 3000sft, same BUA is considered for valuation, since it is within permissible (1.5FAR), any avriation in plan will and actual built will affect the
- 5. Floor wise occupancy and BUA details:
  - 1. GF 01BHJ/UC 1040sft
  - 2. FF 03X01BHK/UC 1385sft
  - 3. SF -01Room./UC 576sft
- 6. Legal aspects are beyond the scope of valuation
- 7. Structural stability is out of scope of valuation
- 8. Stage of Construction:
  - 1. Completed 50% G+01F Structure work Completed
  - 2. Recommended SF Brick work in progress

## 9. NOTE: Subject property not numbered identification probnlem, kindly obtain utility bills on prior

Additional checks for Panchayat properties:-			
Approach Road to the property	Good		
Development of surrounding areas to property	Under Developing		
Distance from city center in Kms	05 Kms		
Distance from corporation limits in Kms/Bus stop in case where there is no Municipal body	01 Km		
Electricity	Yes, Amenities Available in the locality		
Electricity Distributor	NA		
Water supply	Yes, Amenities Available in the locality		
Water Distributor	NA		
Sewer provision	Yes, Amenities Available in the locality		
Sewer line connected to main sewer	Open drain		
Any demolition threat in future development/ expansion	No		
Declaration			

#### I hereby declare that:

- We have no direct/indirect interest in the property valued.
- The information furnished in the report is true and correct to the best of my knowledge.
- The fair market value indicated in the report is an opinion of the value prevailing on the date of the said report and is based on market feedback on values of similar properties. The client is free to obtain other independent opinions on the same. The fair market value of such properties/localities may increase or decrease depending on the future market conditions and scenarios
- The final valuation has been concluded basis comparative market valuation approach and rates are crossverified with the rates prevalent in the nearby localities.



Page No: 4 of 8

Ref No. KV/2024/04/107569



For Seal with Signature	No WIGINEERING SEC
Date: 20-04-2024	K: M See See See See See See See See See S
Place: Bangalore	Tharm . Si





Page No: **5 of 8** Ref No. **KV/2024/04/107569** 



#### Site Image

Applicant Name	Mr.YOGESHA BS
Reference No	DLBAN0HL-04240076971
Address	Property No.60/576, Bili Devalaya Village, Bili Devalaya Village Panchayat, Kunigal Taluk,
	Tumkur District - 572130
















#### Site Image

Applicant Name	Mr.YOGESHA BS
Reference No	DLBAN0HL-04240076971
Address	Property No.60/576, Bili Devalaya Village, Bili Devalaya Village Panchayat, Kunigal Taluk,
	Tumkur District - 572130

# 20. Apr-2024 2.43.45 pm 20. Apr-2024 2.43.45 pm 12. 979568 76.99023 k Lat: 12. 979568 76.99023 k Lon: 76.8352114934393100













#### Annexure

Applicant Name	Reference No
Mr.YOGESHA BS	DLBAN0HL-04240076971

#### location



### Dropped pin





Page No: 8 of 8

Ref No. **KV/2024/04/107569**