

MUNICIPAL CORPORATION OF NORTH DISTRICT

Public Works Department - Road Maintenance & Repair Cell
Official Civil Work Completion & Inspection Order

Report ID: WO-2026-8812

Date: October 01, 2026

Location: Gate 2 Road, North Sector Ring Road

Inspection Status: Inspected and Certified

Contractor: Metro Highway Infrastructure Ltd.

Supervisor ID: ENG-5529

OFFICIAL REPAIR COMPLETION STATEMENT:

This official certificate confirms that road repair work order WO-2026-8812 has been fully executed. The road damage and potholes located at Gate 2 Road, North Sector have been successfully repaired, asphalt resurfaced and sealed. Status: COMPLETED.
The surface was inspected and certified by the civil maintenance engineer on October 01, 2026 as meeting municipal traffic and transit durability guidelines.

STATUS: WORK COMPLETED

Signed: Er. P. K. Verma, Executive Engineer
Municipal Road Works Div, 2026-10-01