3 Main Street

Extend and renovate internally and externally

2017/04/0001S

Mr A Smith

John Doe

Site Report Pro

24 Jul 2020



Project Details



Name: 3 Main Street Client Company: N/A

Summary: Extend and renovate internally and externally Client Name: Mr A Smith

Reference: 2017/04/0001S Client Telephone: 07700900000

Description: Full renovation and extension as per project Client Email: asmith@example.com document reference and planning application

17/6353G

Status: In Progress (27 Apr 2017) Auditor Company: Site Report Pro

Started: 10 Jan 2017 Auditor Name: John Doe

Total Issues: 9



Kitchen Units









Due Date: 05 Jun 2017 Reference: No Reference

Priority: High Location: No Location

Status: In Progress Created: 27 Apr 2017

Tags: Orange

3 Main Street 24 Jul 2020

Description: Kitchen mantle needs to be ordered and fitted to these dimensions

Assigned To: Me

Reviewed By: No Reviewer



Fireplace







Due Date: 07 Jun 2017 Reference: No Reference

Priority: Medium Location: Lounge

Status: In Progress Created: 20 Jan 2017

Tags: Grey Red



3 Main Street 24 Jul 2020

Description: Recess brickwork, install cement board and plaster

Assigned To: No Assignment

Reviewed By: No Reviewer

Comments:

13 May 2017 at 4:26 pm Issue Exported

Assigned: John
Please can you do this work ASAP.


26 Jul 2017 at 4:55 pm

Issue Unlocked



Bathroom Taps





Due Date: 12 Jun 2017 Reference: No Reference

Priority: High Location: Bathroom

Status: New Created: 20 Mar 2017

Tags: Red Green Blue

Description: Re-align tap position, plasterboard, skim and tile

Assigned To: No Assignment

Reviewed By: No Reviewer

Comments:

01 May 2017 at 12:05 pm

Issue Exported Assigned: Tony

Align taps. Plaster in and finish.

26 Jul 2017 at 4:56 pm

Issue Unlocked



Kitchen Trim



Due Date: 14 Jun 2017

Priority: Low

Status: New

Tags: Orange

Description: Trim needs adjusting

Assigned To: Tony

Reviewed By: No Reviewer

Comments: No Comments


Reference: No Reference

Location: Kitchen

Created: 07 Apr 2017



Front Window



Due Date: 20 Jun 2017 Reference: No Reference

Priority: Low Location: Front window

Status: New Created: 01 Apr 2017

Tags: Orange

Description: Fit plastic covers and remove all tape

Assigned To: Joe

Reviewed By: No Reviewer

Comments:

15 May 2017 at 2:59 pm

Issue Exported Assigned: Joe

Please add this to your job list



Replace Chipped Brick



Due Date: 21 Jun 2017 Reference: No Reference

Priority: High Location: Rear extension

Status: New Created: 20 Jan 2017

Tags: Grey

Description: Replace brick before starting next course

Assigned To: John

Reviewed By: No Reviewer



Rendering





Due Date: 23 Jun 2017

Priority: Medium

Status: New

Tags: Red

Description: Repair damaged beading.

Remove exposed woodwork.

Assigned To: Drew

Reviewed By: No Reviewer

Comments: No Comments

Reference: No Reference

Location: Corner of garage

Created: 27 Apr 2017



Drain



Due Date: 23 Jun 2017 Reference: No Reference

Priority: Medium Location: Side passage way

Status: New Created: 18 Feb 2017

Tags: Green

Description: Connect drain to mains drainage and fill hole

Assigned To: Gary

Reviewed By: No Reviewer



Remove Air Vent



Due Date: 26 Jun 2017 Reference: No Reference

Priority: Medium Location: No Location

Status: New Created: 27 Apr 2017

Tags: Grey

Description: Old air vent in master bedroom needs to be removed

Assigned To: Me

Reviewed By: No Reviewer

