



John Doe Site Report Pro 23 Aug 2019

Project Details

3 Main Street

Extend and renovate internally and externally Summary

2017/04/0001S Reference:

Full renovation and extension as per project document reference and planning application 17/6353GDescription:

Status: In Progress (27 Apr 2017)

10 Jan 2017 Started: Mr A Smith Client Name: Client Telephone: 07700900000 asmith@example.com Auditor Company: Site Report Pro Auditor Name: John Doe



Issues



Name: Kitchen Units

Description: Kitchen mantle needs to be ordered and fitted to these dimensions

05 Jun 2017 Due Date: Priority: High In Progress Status: Assigned To: Me



Description: Due Date: Status: Assigned To: Comments:

Name:

Fireplace

Recess brickwork, install cement board and plaster

07 Jun 2017 Medium In Progress No Assignment

13 May 2017 at 4:26 pm Issue Exported Assigned: John Please can you do this work ASAP.

26 Jul 2017 at 4:55 pm Issue Unlocked





Bathroom Taps Description:

Re-align tap position, plasterboard, skim and tile

Due Date: 12 Jun 2017 Priority: High Status: New Assigned To: No Assignment

Comments: 01 May 2017 at 12:05 pm Issue Exported Assigned: Tony Align taps. Plaster in and finish.

26 Jul 2017 at 4:56 pm Issue Unlocked



3 Main Street



Name: Kitchen Trim Trim needs adjusting Description: Due Date: 14 Jun 2017 Priority: Low Status: New

Assigned To: Tony





Comments:

Due Date: 20 Jun 2017 Priority: Low Status: New Assigned To: Joe

15 May 2017 at 2:59 pm Issue Exported Assigned: Joe Please add this to your job list



Replace Chipped Brick Name:

Replace brick before starting next course Description:

Due Date: 21 Jun 2017 Priority: High Status: New John Assigned To:



Drain Name:

Connect drain to mains drainage and fill hole Description:

23 Jun 2017 Due Date: Priority: Medium Status: New Assigned To: Gary





Name: Rendering

Repair damaged beading. Remove exposed woodwork. Description:

23 Jun 2017 Due Date: Medium Priority: Status: New Assigned To: Drew





Name: Remove Air Vent

Description: Old air vent in master bedroom needs to be removed Due Date: 26 Jun 2017

Priority: Medium
Status: New
Assigned To: Me

