

WO #S2-32819

Approved

Staging Heavy Duty - 9919

Customer: Savannah Tran
Company: 4 Star Truck Repair
VIN: PV1T2SK1DNUUK7YDE
Date: Sep 10, 2026
Service Advisor: Admin ShopView

Vehicle: 2011 Hyundai Santa Fe
Unit: 665
Licence Plate: ZZP-6028

	Name/Description	Actual/Estimate	Status
1	Replace - Brake pot	0.00 / 1.50	Approved
Parts	(N231-013BR) X107-A 1/8" EXTRUDED BRASS STREET TEE	2	
	Misc hardware/ fittings	1	
	Brake pot	1	
2	Replace - Brake pot	0.00 / 1.50	Approved
Tech Story	ZZAUTOTEST short note for the printed page.		
Parts	Brake pot	1	
	Misc hardware/ fittings	1	
3	Replace - Brake pot	0.00 / 1.50	Approved
Tech Story	ZZAUTOTEST long note. The technician found excessive play in the steering linkage and recommends replacing the drag link and both tie rod ends before the unit returns to service. The technician found excessive play in the steering linkage and recommends replacing the drag link and both tie rod ends before the unit returns to service. The technician found excessive play in the steering linkage and recommends replacing the drag link and both tie rod ends before the unit returns to service. The technician found excessive play in the steering linkage and recommends replacing the drag link and both tie rod ends before the unit returns to service. The technician found excessive play in the steering linkage and recommends replacing the drag link and both tie rod ends before the unit returns to service. The technician found excessive play in the steering linkage and recommends replacing the drag link and both tie rod ends before the unit returns to service. The technician found excessive play in the steering linkage and recommends replacing the drag link and both tie rod ends before the unit returns to service.		
Parts	Brake pot	1	
	Misc hardware/ fittings	1	

Total Actual Time: 0.00
Total Estimated Time: 4.50

Printed: Sep 10, 2026 04:44 AM