

Summary report

Wellbore: 15/9-F-15 D

Period: 2013-11-12 00:00 - 2013-11-13 00:00

Status:	normal
Report creation time:	2018-05-03 13:52
Report number:	3
Days Ahead/Behind (+/-):	
Operator:	Statoil
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Maersk Drilling
Spud Date:	2013-11-10 14:00
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature (I):	
Pressure (I):	
Date Well Complete:	2013-12-02

Dist Drilled (m):	362
Penetration rate (m/h):	-999.99
Hole Dia (in):	17.5
Pressure Test Type:	formation integrity test
Formation strength (I):	
Dia Last Casing (I):	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMd:	2032
Depth mTVD:	1958
Plug Back Depth mMD:	
Depth at formation strength mMD:	
Depth At Formation Strength mTVD:	
Depth At Last Casing mMD:	1368.4
Depth At Last Casing mTVD:	1340.4

Summary of activities (24 Hours)

Drilled 17 1/2" hole from 1670 m to 2032 m.
Waited on weather.

Summary of planned activities (24 Hours)

Wait on weather.

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	13:45	2002	drilling -- drill	ok	Drilled 17 1/2" hole from 1670 m to 2002 m with 4000-4430 liter/min, 260-282 bar, 140 rpm, 12-21 kNm, ROP 31-38 m/hr, WOB 1-12 ton, ECD 1,418-1,429 sg, Max gas 0,85%. At 13:30 the Ocean Pride disconnected cuttings hose due to bad weather. Meanwhile picked up and racked back 13 3/8" casing in derrick. Observed leaking pipe on ISO tank #3, stopped drilling.
13:45	18:00	1889	interruption -- other	ok	Repaired leaking pipe on ISO tank #3. Meanwhile: Circulated hole clean with 4500 liter/min, 280 bar. 3 x bottoms up. Racked back one stand each bottoms up.
18:00	21:15	1970	interruption -- other	ok	Repaired leaking pipe on ISO tank #3. Meanwhile: RIH with 17 1/2" BHA from 1889 m to 1929. Established circulation with 500 liter/min, 5 bar, 30 rpm, 8 kNm. Reciprocated string between 1929 m and 1970 m.
21:15	21:30	2002	drilling -- ream	ok	Washed down with 17 1/2" BHA from 1970 m to 2002 m with 4450 liter/min, 292 bar, 140 rpm, 10 kNm.
21:30	23:00	2032	drilling -- drill	ok	Drilled 17 1/2" hole from 2002 m to 2032 m with 4450 liter/min, 296 bar, 140 rpm, 10-24 kNm, ROP 35-36 m/hr, WOB 3-6 ton, ECD 1,410 sg. Max gas 0,41%.
23:00	00:00	2032	drilling -- circulating conditioning	ok	Circulated hole clean with 4500 liter/min, 280 bar. 3 x bottoms up. Racked back one stand each bottoms up.

Drilling Fluid

Sample Time	03:00	09:00	15:00	21:30
Sample Point	Flowline	Flowline	Flowline	Flowline
Sample Depth mMD	1539	1888	2003	2003
Fluid Type	Enviromul Yellow	Enviromul Yellow	Enviromul Yellow	Enviromul Yellow
Fluid Density (g/cm3)	1.4	1.4	1.4	1.4
Funnel Visc (s)	-999.99	-999.99	-999.99	-999.99
Mf (I)				
Pm (I)				
Pm filtrate (I)				
Chloride (I)				
Calcium (I)				
Magnesium (I)				
Ph				
Excess Lime (I)				
Solids				
Sand (I)				
Water (I)				
Oil (I)				
Solids (I)				
Corrected solids (I)				
High gravity solids (I)				
Low gravity solids (I)				
Viscometer tests				
Plastic visc. (mPa.s)	36	33	35	35
Yield point (Pa)	9	10	9	10

Filtration tests				
Pm filtrate ()				
Filtrate Lthp ()				
Filtrate Hthp ()				
Cake thickn API ()				
Cake thickn HPHT ()				
Test Temp HPHT (degC)	120	120	120	120
Comment				

Pore Pressure

Time	Depth mMD	Depth TVD	Equ Mud Weight (g/cm3)	Reading
00:00	1380		1.03	estimated
00:00	2003		1.03	estimated

Survey Station

Depth mMD	Depth mTVD	Inclination (dega)	Azimuth (dega)	Comment
1712.7	1667.7	16.89	323.84	
1753.2	1706.3	18.95	335.44	
1792.9	1743.6	20.66	344.61	
1833.5	1781.3	22.98	351.87	
1874	1818.3	25.39	357.35	
1914.8	1854.9	27.17	2.38	
1955.1	1890.3	29.95	3.22	
1995.5	1925.2	30.21	3.94	

Lithology Information

Start Depth mMD	End Depth mMD	Start Depth TVD	End Depth TVD	Shows Description	Lithology Description
1600	2000				Claystone with traces of Dolomite and Limestone