

Summary report

Wellbore: 15/9-F-1 C

Period: 2014-04-01 00:00 - 2014-04-02 00:00

Status:	normal
Report creation time:	2018-05-03 13:51
Report number:	40
Days Ahead/Behind (+/-):	
Operator:	Statoil
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Maersk Drilling
Spud Date:	2014-02-21 14:30
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature (I):	
Pressure (I):	
Date Well Complete:	2014-03-15

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia (I):	
Pressure Test Type:	formation integrity test
Formation strength (g/cm3):	1.6
Dia Last Casing (I):	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMd:	4094
Depth mTVD:	3180.5
Plug Back Depth mMD:	
Depth at formation strength mMD:	3059
Depth At Formation Strength mTVD:	2874.4
Depth At Last Casing mMD:	4087.1
Depth At Last Casing mTVD:	3178

Summary of activities (24 Hours)

Waited for equipment to arrive. Displaced well down to 160 m to drillwater. Installed Bowl protector.
RIH with camera and recorded in the Subsea WH area to evaluate condition of threads. POOH with camera.
Cleaned pits and mixed new Packer Fluid. RIH to 180 m and displaced back to Packer Fluid. POOH.
R/U for running 10 3/4". RIH with Tieback Adapter and joint to 15 m.

Summary of planned activities (24 Hours)

M/U Tieback Adapter and POOH with setting tool.
P/U Adjustable sub setting tool and RIH. Adjust. POOH with setting tool.
Pressure test Tieback connection. Set MS-T seal. Test same.
Run Bowl protector. Rig down casing handling equipment.
P/U Safelock RT and RT and pull plug at 641 m. POOH with same.
Pull Bowl protector.
R/U for running tubing.

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	09:00	121	interruption -- repair	ok	Waited for equipment. Meanwhile performed daily checks and PMs. Washed down in Pump room, Sack store and Moonpool Removed ROV equipment from Moonpool.
09:00	09:15	121	interruption -- other	ok	Held TBT for displacement job
09:15	10:00	121	interruption -- other	ok	Filled pits with drill water.
10:00	10:45	160	interruption -- other	ok	Positioned string at 160 m and displaced to drill water with 2000 LPM/6 bar. Pumped 74 m3.
10:45	11:00	40	interruption -- other	ok	POOH from 160 to 40 m.
11:00	11:15	0	interruption -- other	ok	Strapped out last stand.
11:15	11:45	0	interruption -- repair	ok	RIH to 20,52 m to set Bowl protector. Strapped out to confirm depth.
11:45	13:15	0	interruption -- repair	ok	Assisted in rigging up downhole camera equipment on drill floor.
13:15	13:30	0	interruption -- repair	ok	Held TBT
13:30	14:15	139	interruption -- repair	ok	RIH with camera on 5 1/2" DP to 139 m.
14:15	15:15	139	interruption -- repair	ok	Positioned camera at 139 m. Circulated with 200 - 900 LPM and adjusted depth as instructed. Recorded condition of Subsea Hanger 11 1/4" OD 2 TPI threads
15:15	15:45	0	interruption -- repair	ok	POOH with Camera on 5 1/2" DP from 139 m to surface.
15:45	16:15	0	interruption -- repair	ok	Rigged down camera equipment and L/D same.
16:15	16:30	0	interruption -- repair	ok	M/U Bowl protector RT and RIH to 20,52 m. POOH with Bowl protector.
16:30	16:45	0	interruption -- repair	ok	L/D bowl protector and P/U Jetting sub.
16:45	17:00	180	interruption -- other	ok	RIH with Jetting assy on 5 1/2" DP to 180 m
17:00	21:00	180	interruption -- other	ok	Cleaned out pits due to limited available clean pits. Mixed new 1,03 SG NaCl brine. Meanwhile prepared for running Tieback string. Cleaned on drill floor and in shaker room.
21:00	21:15	180	interruption -- other	ok	Held TBT
21:15	21:30	180	interruption -- other	ok	Displaced well from 180 m and up to 1,03 SC NaCl Packer Fluid.
21:30	22:00	0	interruption -- other	ok	POOH with Jetting assy from 180 m to surface. L/D Jetting sub.
22:00	23:00	0	interruption -- repair	ok	Held TBT for R/U handling equipment for 10 3/4" Tieback and rigged up same.
23:00	23:15	0	interruption -- repair	ok	Held TBT for casing running.
23:15	00:00	15	interruption -- repair	ok	P/U and RIH 10 3/4" Tieback Adapter and joint to 15 m. Checked Adapter.

Drilling Fluid

Sample Time	21:00
Sample Point	Active pit
Sample Depth mMD	4094
Fluid Type	NaCl brine
Fluid Density (g/cm3)	1.03
Funnel Visc (s)	-999.99
Mf (I)	
Pm (I)	
Pm filtrate (I)	
Chloride (I)	
Calcium (I)	
Magnesium (I)	

Ph	
Excess Lime ()	
Solids	
Sand ()	
Water ()	
Oil ()	
Solids ()	
Corrected solids ()	
High gravity solids ()	
Low gravity solids ()	
Viscometer tests	
Plastic visc. (mPa.s)	-999.99
Yield point (Pa)	-999.99
Filtration tests	
Pm filtrate ()	
Filtrate Lthp ()	
Filtrate Hthp ()	
Cake thickn API ()	
Cake thickn HPHT ()	
Test Temp HPHT ()	
Comment	