

MyDesign Portfolio

Element I

Test 1: Cable Trough Fit (High Priority)

Tested by placing the CT into the alley behind the computers that's filled with cables and seeing how well it fit in between the desks and the Back wall.

Consisted of 1 test. Results were singular in that the Cable Trough fit perfectly and our measurements fit within the constraints of the space.

Test 2: Strength of Cable Trough (High Priority)

Tested by having three different people of varying sizes on the Cable Troughs.

Consisted of 3 tests. Results were the CTs withstood the full force of all three people even as they lightly jumped and moved around on the CTs.

Test 3: Cable Troughs Connectability (High Priority)

Tested by applying a connection point and testing its stability and ability to stay on through movement.

Consisted of 2 tests. Results were the CT Connectors stood still and remained between the CTs while being stepped on and moved around.

Test 4: Cable Trough Stability (High Priority)

Tested by a person shifting their weight from side to side while standing on the CT.

Consisted of 1 test. Results were the Cable Trough didn't flip over or slip around. This was due to the placement of its pegs with gripping friction pads beneath them.

Test 5: Cable Trough Portability (High Priority)

Tested by stacking the CTs and placing them on a shelf.

Consisted of 1 test. Results were the CTs easily within most spaces we put them in due to their ergonomic design.