

Inspection Report

Inspection summary

Tank / container reference	EXAMPLE-001
Company	Example Company
Site / location	Example Site
Inspection ID	SAMPLE-INSPECTION
Analysis completed (UTC)	2026-09-27 17:39:00
Report generated (UTC)	2026-09-28 10:00:00

AI assessment

DIRTY

Review the indicated media and inspect the container before deciding on the next step.

Dirty score: 0.5646 / 1

Model score; not a confidence percentage.

Media analysed

Photos: 1 | Videos: 0 | Sampled video frames: 0

Inspector assessment

Awaiting inspector review

No inspector assessment has been recorded for this inspection.

This report records the AI assessment and any separately recorded inspector assessment. It does not itself certify cleanliness.

Inspection evidence

All assessed photos and sampled frames, in inspection order.

01 Photo | Highest dirty score



tank-interior-frame.jpg

DIRTY | Dirty score: 0.5646 / 1

Technical appendix

The report uses the scores and decision settings captured when this inspection completed. Downloading it does not run a new analysis.

Report revision	1
Dirty threshold	0.3500
Clean threshold	Automatic CLEAN disabled
Decision policy	manual-review-v1
Model version	bdecba82014b3ba00db5e9eac2ef06216ab0bef9be14a8c12a0a4e4c662a2806

Model family	Dirty score	Result
EfficientNet-B0	0.5646	DIRTY
ConvNeXt-Tiny	0.3276	NEEDS MANUAL REVIEW
EfficientNetV2-S	0.4195	DIRTY
DINOv2-S	0.4357	DIRTY

Images are embedded previews. Original video files are not included.
Generated by Bitquanta. This document is not digitally signed.