


dig-s1





DANGE TO THE CONTRACTOR

ziffer_resize/NaN_1_dig0001_20211111-160932.jpg -1 2
ziffer_resize/NaN_2_dig001_20211111-075800.jpg -1 3
ziffer_resize/NaN_3_dig0001_20211111-060800.jpg -1 3
ziffer_resize/NaN_3_dig0001_20211125-224921.jpg -1 3
ziffer_resize/NaN_4_dig0001_20211112-095614.jpg -1 3
ziffer_resize/NaN_5_dig0001_20211111-124825.jpg -1 5
ziffer_resize/NaN_7_dig0001_20211203-131442.jpg -1 9
ziffer_resize/NaN_7_dig001_20211111-052300.jpg -1 8



Total number of images: 694 Number of bad images: 8

Percentage of good images: 98.8%