

Table 1-A
SMWU 332 Monitoring Well Inspection/Maintenance Summary
2025 Monitoring Well Inspection Memorandum
Former England Air Force Base, Louisiana

Well ID	Annual (A)/ Biennial (B)/ Gauging (G)	Construction Details						Field Measurements			Calculated Measurements			Maintenance			Miscellaneous		Inspection Date
		Northing	Easting	Top of Casing (ft NAVD)	Ground Surface (ft NAVD)	Screen Interval (ft bgs)	Total Depth (ft bgs)	Depth to Water (btoc)	Total Depth (btoc)	Top of Pump (btoc)	Groundwater Elevation (ft NVAD)	Total Depth Difference (ft)	Water Column Thickness (ft)	Well Maintenance Performed	Repaired/ Reset Bollard(s)	Removed Vegetation from Well Area	Photo Number(s) (Attachment 3A)	Notes	
Shallow Zone Wells ¹																			
BH01MW02	G	299127.17	3270060.12	87.89	87.90	19.8 - 29.8	30.1	12.02	29.84	-	75.87	-0.25	18.07	Labeled Well	NA	NO	56, 57	Missing a bolt	9/16/2025
BH01MW04	G	299108.65	3270214.17	81.33	81.18	19.5 - 29.5	29.8	5.69	28.97	-	75.64	-0.98	24.26		NA	NO	60, 61		9/16/2025
BH01MW06	G	299203.26	3270281.42	78.59	78.50	24.1 - 34.1	34.4	4.23	34.11	-	74.36	-0.38	30.26		NA	NO	64, 65		9/16/2025
Intermediate Zone Wells ²																			
A39G012MW	B	297758.64	3271867.12	85.14	85.57	63 - 73	78	10.15	75.75	-	74.99	-1.82	67.42		NA	NO	1, 2		9/18/2025
A39L005PZ	G	299241.13	3269010.07	85.51	85.63	59.2 - 69.2	71.88	10.79	123.89	-	74.72	52.13	60.97	Labeled Well	NA	NO	7		9/22/2025
A39L006PZ	G	299884.38	3269425.69	84.69	84.93	61.8 - 71.8	74.56	10.74	73.44	-	73.95	-0.88	63.58		NA	NO	8		9/20/2025
A39L009PZ	G	300393.80	3268547.15	84.15	84.15	64.4 - 74.1	74.48	49.94	72.15	-	34.21	-2.33	24.54	Labeled Well	NA	NO	13, 14		9/20/2025
A39L010PZ	G	298815.46	3271764.43	86.93	87.21	55 - 65	67	12.16	67.20	-	74.77	0.48	54.56		NA	NO	15, 16		9/17/2025
A39L011PZ	B	298075.28	3271345.05	88.31	88.54	40 - 50	52	12.94	52.00	-	75.37	0.23	38.83	Pump pulled	NA	YES	17, 18		9/18/2025
A39L013DP	G	300665.46	3269065.48	84.74	84.88	40 - 50	50.72	10.02	50.44	-	74.72	-0.14	40.56	Labeled Well	NA	NO	19, 20		9/20/2025
A39L013PZ	G	297286.01	3270548.22	86.20	86.62	60 - 69.8	70			-	86.20	-69.58	69.58		-	-	-		-
A39L014DP	A	301070.93	3269750.68	85.19	86.76	40 - 50	50.5	10.50	39.81	-	74.69	-9.12	38.43	Labeled Well	NA	NO	21, 22		9/18/2025
A39L014PZ*	G	298616.27	3269451.23	86.23	86.44	60 - 70	72	10.47	71.00	-	75.76	-0.79	61.32		-	-	23		10/1/2025
A39L015PZ	G	300669.06	3271990.76	84.01	84.66	59 - 69	71.7	9.36	73.02	-	74.65	1.97	61.69	Pump pulled	NA	YES	24, 25		9/20/2025
A39L017PZ	G	299882.57	3270254.89	85.46	85.57	58 - 67.1	70	10.52	62.79	-	74.94	-7.10	59.37		NA	NO	26, 27		9/20/2025
A39L018PZ	G	299421.70	3270366.92	78.74	75.54	40 - 50	52.7	4.91	51.91	-	73.83	-3.99	50.99	Painted Stick up	NA	YES	28, 29		9/20/2025
A39L019PZ	A	299437.40	3271153.19	87.84	88.50	60 - 70	72	12.74	55.81	-	75.10	-15.53	58.60		NA	NO	30, 31	Has a cap instead of a j-plug	9/17/2025
A39L036DPR2	A	299907.90	3267996.11	88.97	89.02	59 - 69	71.5	13.47	58.00	-	75.50	-13.45	57.98		NA	NO	39, 40		9/16/2025
A39L039DP	B	300731.06	3267299.84	82.31	82.33	52.7 - 62.6	65.3	7.94	64.76	-	74.37	-0.52	57.34		NA	NO	41		10/7/2025
A39L073DP	A	299269.23	3272386.21	84.24	84.65	63.7 - 73.6	74	9.30	70.29	-	74.94	-3.30	64.29	Water in vault removed, pump pulled.	NA	NO	42		9/16/2025
A39MW093	G	301563.20	3268938.72	84.21	84.52	38 - 48	49	9.45	48.01	-	74.76	-0.68	39.24	Water in vault removed, pump pulled.	NA	NO	47		10/6/2025
A39MW095	G	302010.33	3269621.50	84.52	84.48	54.2 - 64.2	64.5	10.50	63.90	-	74.02	-0.64	54.04		NA	NO	49		10/6/2025
A39MW096	A	302318.95	3269765.90	82.41	82.64	60 - 70	70.3	8.84	69.67	-	73.57	-0.40	61.23		NA	NO	50, 51		9/17/2025
A39MW097	A	302076.25	3269909.73	83.60	83.81	54.7 - 64.7	65			-	83.60	-64.79	64.79		-	-	52		
A39MW098	A	301773.61	3269790.92	84.18	84.39	54.5 - 64.5	65	10.94	64.49	-	73.24	-0.30	53.85		NA	NO	53		10/7/2025
BH01MW01	G	299135.27	3270061.50	87.99	87.94	39.5 - 49.5	50	12.33	39.78	-	75.66	-10.27	37.72	Labeled Well	NA	NO	54, 55		9/17/2025
BH01MW03	G	299117.20	3270216.64	81.01	80.99	39.4 - 49.4	50	5.72	49.61	-	75.29	-0.41	44.30		NA	NO	58, 59		9/17/2025
BH01MW05	G	299211.92	3270283.75	78.74	78.65	39.6 - 49.6	50.5	3.26	49.71	-	75.48	-0.88	47.33		NA	NO	62, 63	Missing a bolt	9/17/2025
SS45L001MW	A	300887.79	3268800.32	83.25	83.37	54 - 64	67	7.80	67.00	-	75.45	0.12	59.08	Water in vault removed.	NA	NO	68	Well Lid Cracked	10/6/2025
SS45L005MW	G	299647.82	3269138.15	85.25	85.35	56 - 66	69	10.24	68.54	-	75.01	-0.36	58.66	Labeled Well	NA	NO	70, 71	Missing bolts	9/22/2025
SS45L006MW	G	297424.17	3272747.59	87.77	87.93	57 - 67	70	13.72	70.00	-	74.05	0.16	56.12		NA	NO	72, 73	Missing j-plug.	9/17/2025
Well #03	B	299693.44	3271604.53	88.58	85.72	65 - 74.5	78	13.73	75.00	-	74.85	-5.86	67.13	LOCK REPLACED, BOLLARDS AND STICK UP PAINTED, PULLED PUMP	NA	YES	75, 76		9/17/2025
Well #04	G	299228.07	3271854.11	86.88	87.31	62 - 71.5	75	14.44	65.89	-	72.44	-8.68	60.13		NA	NO	77, 78		9/22/2025
Well #05	B	298525.52	3271523.04	85.57	82.64	50 - 59.5	61	11.34	62.90	-	74.23	-1.03	52.59	LOCK REPLACED, BOLLARDS AND STICK UP PAINTED, PULLED PUMP	NA	NO	79, 80	3 bollards leaning	9/18/2025
Well #06	B	297615.49	3271633.24	83.44	80.43	50 - 59.5	61	8.40	63.00	-	75.04	-1.01	55.61	LOCK REPLACED, BOLLARDS AND STICK UP PAINTED, PULLED PUMP	NO	YES	81, 82	1 bollard leaning	9/18/2025
Well #07	G	297628.81	3271071.77	91.19	88.22	50 - 59.5	61	16.26	NA	-	74.93	NA	47.71	Lock replaced.	NA	NO	83, 84	Pump stuck in well, Casing bent and unabel to remove.	9/23/2025
Well #08	A	298158.76	3272121.69	91.21	87.83	69 - 78.5	80	16.34	82.00	-	74.87	-1.38	67.04	Lock replaced, paineted bollards	NA	NO	85, 86		9/17/2025
Well #09	G	299693.52	3272372.01	84.14	84.25	--	75	9.47	71.30	-	74.67	-3.59	65.42	Pump pulled	NA	NO	87		9/16/2025
Well #11	A	300733.01	3268872.00	87.09	83.99	70 - 79.5	80	12.40	73.24	-	74.69	-9.86	70.70	Painted Bollards, Replaced lock	NO	YES	88, 89		9/18/2025

Table 1-A
SMWU 332 Monitoring Well Inspection/Maintenance Summary
2025 Monitoring Well Inspection Memorandum
Former England Air Force Base, Louisiana

Well ID	Annual (A)/ Biennial (B)/ Gauging (G)	Construction Details						Field Measurements			Calculated Measurements			Maintenance			Miscellaneous		Inspection Date
		Northing	Easting	Top of Casing (ft NAVD)	Ground Surface (ft NAVD)	Screen Interval (ft bgs)	Total Depth (ft bgs)	Depth to Water (btoc)	Total Depth (btoc)	Top of Pump (btoc)	Groundwater Elevation (ft NVAD)	Total Depth Difference (ft)	Water Column Thickness (ft)	Well Maintenance Performed	Repaired/ Reset Bollard(s)	Removed Vegetation from Well Area	Photo Number(s) (Attachment 3A)	Notes	
Well #13	A	301195.91	3269450.20	87.28	84.53	70 - 79.5	81	12.72	73.03	-	74.56	-10.72	71.03	Painted Bollards, Replaced lock	NA	YES	92, 93	One bollard leaning	9/19/2025
Well #15	A	301088.36	3269047.49	87.03	83.53	60 - 69.5	71	12.15	73.48	-	74.88	-1.02	62.35	Painted Bollards, Replaced lock	NA	YES	95		9/22/2025
Well #17	A	301820.40	3269306.59	84.16	84.82	55 - 64.5	66	9.95	65.00	-	74.21	-0.34	55.39		NA	NO	96		10/6/2025
Well #19*	G	301928.19	3268378.70	84.05	84.54	70 - 79.5	81	8.89	81.81	-	75.16	1.30	71.62		NA	NO	98		9/30/2025
Well #21*	G	302141.85	3269397.22	83.61	83.99	75 - 84.5	85	9.06	127.92	-	74.55	43.30	75.56		NA	NO	100		9/30/2025
Well #22	B	300687.31	3270146.95	86.09	86.45	--	51	11.42	41.25	-	74.67	-9.39	39.22	Labeled Well	NA	NO	101, 102		9/19/2025
Well #23	A	298737.80	3272389.14	86.03	85.70	--	71	11.00	75.94	-	75.03	4.61	60.33	Pump pulled	NA	NO	103, 104		9/16/2025
Well #24R*	G	299637.07	3266577.71	82.20	82.33	55.4 - 64.4	66.4	6.34	65.92	-	75.86	-0.35	59.93		-	-	105		9/30/2025
Well #25	A	297664.34	3272415.36	86.61	86.68	58 - 68	70	11.60	72.80	-	75.01	2.87	58.33	Pump pulled	NA	NO	106, 107		9/17/2025
Well #26	A	298722.50	3272549.66	86.94	86.99	63 - 73	78	12.03	75.40	-	74.91	-2.55	65.92	Pump pulled	NA	NO	108, 109		9/16/2025
Well #27	G	300046.18	3272097.40	83.09	83.21	63 - 73	78	8.55	77.47	-	74.54	-0.41	69.33	Pump pulled	NA	YES	110, 111		9/20/2025
Well #28	G	300115.05	3271648.82	87.32	87.70	64.6 - 74 - 6	77.13	12.63	78.02	-	74.69	1.27	64.12	Pump pulled, labeled well	NA	NO	112, 113		9/20/2025
Well #29	G	300392.48	3271654.25	83.04	83.22	63 - 73	75.16	8.49	76.32	-	74.55	1.34	66.49	Pump pulled, labeled well	NA	NO	114, 115		9/20/2025
Deep Zone Wells ³																			
A39L001PZ*	G	301547.75	3268912.00	84.29	84.71	88.1 - 97.8	130	9.97	99.90	-	74.32	-29.68	119.61		NA	NO	3		9/30/2025
A39L002PZ*	G	300715.42	3267308.72	82.13	82.24	95.5 - 105.5	122	7.96	106.10	-	74.17	-15.79	113.93		NA	NO	4		10/1/2025
A39L003PZ	G	299941.47	3267905.73	86.94	86.77	110 - 120	126.5	12.38	122.29	-	74.56	-4.38	114.29	Labeled Well	NA	NO	5, 6		9/19/2025
A39L007PZ	B	299901.15	3269422.49	84.73	84.92	105.2 - 115	120	10.11	119.65	-	74.62	-0.16	109.70	Labeled Well	NA	NO	9, 10		9/19/2025
A39L008PZ	G	301080.28	3269764.50	85.09	85.28	108 - 118	121	10.57	122.16	-	74.52	1.35	110.24	Labeled Well	NA	NO	11, 12		9/20/2025
A39L020PZ	G	299448.04	3271157.53	87.94	88.81	110 - 120	123	13.34	124.16	-	74.60	2.03	108.79	Labeled Well, Replaced bolt	NA	NO	32, 33		9/20/2025
A39L022PZ*	G	298608.69	3269447.96	86.23	86.41	110 - 119.8	124	11.91	130.60	-	74.32	6.78	111.91		-	-	34		10/1/2025
A39L027DP	A	300405.08	3268539.69	83.62	83.88	111 - 121	121.5	9.07	112.72	-	74.55	-8.52	112.17	Labeled Well	NA	NO	35, 36		9/18/2025
A39L028DP	A	300821.04	3269109.19	84.84	84.70	113.4 - 123.4	124	10.31	114.86	-	74.53	-9.28	113.83	Labeled Well	NA	NO	37, 38		9/18/2025
A39L082DP	B	298809.87	3271767.17	87.19	87.15	108.3 - 118.3	140	13.50	118.30	-	73.69	-21.74	126.54		NA	NO	43, 44	Missing a bolt	9/17/2025
A39L092DP	B	301563.20	3268938.72	88.27	88.50	113 - 123	128	13.53	125.45	-	74.74	-2.32	114.24	Tubing Pulled	NA	YES	45, 46		9/18/2025
A39MW094	A	301809.02	3268955.65	84.29	84.65	91 - 101	103	8.45	101.35	-	75.84	-1.29	94.19		NA	NO	48		10/7/2025
SS45L002MW	A	301809.02	3268955.65	83.08	83.27	89 - 99	101.86	8.80	101.90	-	74.28	0.23	92.87		NA	NO	69		10/7/2025
SS45L007MW	G	302569.21	3269208.89	80.88	80.90	94 - 104	105	7.55	103.78	-	73.33	-1.20	97.43		NA	NO	74		10/8/2025
Well #12	A	300725.79	3268859.32	86.71	83.97	90 - 99.5	102	12.19	91.90	-	74.52	-12.84	92.55	Painted Bollards, Replaced lock	NA	YES	90, 91		9/18/2025
Well #14*	A	301097.96	3269063.23	86.41	83.73	90 - 99.5	101	11.95	101.41	-	74.46	-2.27	91.73	Painted Bollards, Replaced lock	NO	YES	94	One bollard leaning	9/30/2025
Well #18*	A	301944.03	3268400.17	84.05	84.39	90 - 99.5	103	10.20	102.00	-	73.85	-0.66	92.46		NA	NO	97		9/30/2025
Well #20	A	301735.04	3269033.05	83.36	84.63	120 - 129.5	130	9.10	127.92	-	74.26	-0.81	119.63		NA	NO	99		10/7/2025
Injection Wells																			
SS45IW001*	G	301824.11	3269315.34	83.02	83.67	55.5-65.5	68	10.37	67.46	-	72.65	0.11	56.98		NA	NO	66		9/30/2025
SS45IW002	G	302014.16	3269632.28	82.91	83.78	55.5-65.5	70			-	82.91	-69.13	69.13		-	-	69		

Notes:
¹ Shallow wells are screened in the fine-grained deposits of the upper 40 feet of the Red River Alluvium.
² Intermediate wells are screened in the coarser-grained deposits of the Red River Alluvium between 40 and 80 feet bgs.
³ Deep wells are screened in the Miocene Aquifer between 90 and 120 feet below ground surface.
-- Value not available
* Due to access restrictions, inspection and field measurements were collected during PFAS gauging.
Grayed Highlight - Well was not found during inspection activities.

bgs - Below ground surface
btoc - Below top of casing
ft - Feet
NAVD - North American Vertical Datum 88