



ELECTRICAL RELIABILITY PROGRAM

POWER SAFETY. ONE DASHBOARD. FOR LIFE.

Arc Flash Analysis · Infrared Thermography · Switchgear Maintenance — for one location or 1,000. You send the facility list. We handle everything else.

NFPA 70B

NFPA 70E

OSHA

IEEE 1584

AHJ · STATE · CITY

WHY · THE PROBLEM

COMPLIANCE SHOULDN'T BE YOUR FULL-TIME JOB

NFPA 70B is now a standard — electrical maintenance is no longer optional. And it never comes alone:

NEC · NFPA 70

NFPA 70B

NFPA 70E

NFPA 99

NFPA 101

NFPA 110

OSHA 29 CFR 1910

IEEE 1584

ANSI/NETA MTS

IFC

JOINT COMMISSION · CMS

INSURANCE CARRIER REQ'S

AHJ · STATE · CITY

Each with its own cycle, its own documentation, and its own inspector. Complicated and overwhelming is the honest description.

Electrical systems change constantly. Studies go stale. Labels expire. Records scatter across binders, inboxes, and vendors. And the failures that hurt most — a loose connection, an overheating breaker, a deteriorating switchgear bus — start long before anything looks wrong.

Don't sweat it. Send FSG your facility list and square footage. One location or 1,000 — we take care of all the details: budget, schedule, planned maintenance, routine maintenance, and every report, finding, and price in one place. For life.

YOUR GUIDE

A PARTNER WHO'S DONE THIS FOR FOUR DECADES

You know your operation. We know electrical reliability. FSG's engineering and service teams keep your people safe, your equipment running, and your records audit-ready — so your team stays focused on the business.

45+

YEARS IN THE ELECTRICAL FIELD

43+

LOCATIONS NATIONWIDE

Top 2%

NATIONALLY RANKED ELECTRICAL
CONTRACTOR

NFPA

CERTIFIED ENGINEERS ACROSS ALL REGIONS

WHAT · THREE SERVICES, ONE PROGRAM

FIND IT EARLY. FIX IT PLANNED. PROVE IT FOREVER.

ARC FLASH ANALYSIS

Know the risk. Protect your people.

- Incident energy analysis per IEEE 1584-2018
- Short-circuit & protective device coordination studies
- NFPA 70E-compliant arc flash labels
- Facility-wide PPE selection matrix
- Updated as your system changes — 70E requires it

IR THERMOGRAPHY

See failures weeks before they happen.

- Scanned energized, under normal load — no shutdown
- Finds loose connections, overloaded circuits, failing breakers
- Thermal images with severity classifications
- Recommended corrective actions, prioritized
- Fewer emergency calls, smarter maintenance planning

SWITCHGEAR MAINTENANCE

Reliability for the gear that runs everything.

- Preventive programs aligned with recognized testing standards
- Counters heat, dust, vibration, moisture, and wear
- Reduces breaker failure and arc flash risk
- Extends equipment life, cuts unplanned downtime
- Documentation that supports capital planning

HOW · THE PLAN

THREE STEPS. THEN IT RUNS FOR LIFE.

1

SEND YOUR FACILITY LIST

Locations and square footage. That's it. One building or a 1,000-site portfolio — the program scales either way.

2

WE HANDLE THE DETAILS

Budget, schedule, planned and routine maintenance, code requirements by jurisdiction. Our people and our technology do the work.


3

EVERYTHING IN ONE PLACE

Every report, finding, quote, and price lands on your live dashboard — organized by site, severity, and status. For life.


The dashboard is the value we bring — at no additional cost. We charge only for the labor. The visibility comes with it.

LIVE ACTION AS IT HAPPENS. ALL IN ONE PLACE.




MAP VIEW. EVERY SITE, NATIONWIDE – ACTIVE, COMPLETED, AND NO-WORK-ORDER STATUS AT A GLANCE. CLICK ANY SITE TO DRILL DOWN.

YOUR WHOLE PROGRAM YEAR ON ONE SCREEN



PROGRAM SUMMARY. SCAN PROGRESS AND PROBLEM SEVERITY ACROSS EVERY BUILDING – CRITICAL TO COMPLIANCE, COUNTED LIVE.

KNOW WHAT NEEDS ATTENTION FIRST




SEVERITY DISTRIBUTION. FINDINGS RANKED BY SEVERITY LEVEL, UPDATED AS SCANS COMPLETE.

EVERY SITE'S FULL BREAKDOWN, ONE HOVER AWAY

Items by Location

Problem Items by Location

Top locations by total severity items (stacked)



SEVERITY CODES: 1 Critical 2 Serious 3 Important 4 Minor 5 Visual 6 Compliance

DRILL DOWN BY LOCATION. PROBLEM ITEMS STACKED BY SITE AND SEVERITY – HOVER ANY LOCATION FOR THE DETAIL.



FINDING → QUOTE → REPORT. ONE CLICK EACH.

Dashboard

Projects

Jobs

Work Orders

Material Orders

Locations

IR Summary

Work Order Report

Customer Access

Medical Facility

Jan 1, 2026 - Sep 29, 2026

Medical Facility

Medical Facility

IR Thermographic Program Summary

3 Locations · Reporting Type: Anomaly · As of September 29, 2026

Program Year 2026

IR Thermographic Program Summary

Site List

All IR Reports

Location	Full	Partial	Critical	Serious	Important	Minor	Visual	Compliance	Total
Prospect Tustin II 14642 Newport Avenue, Tustin, CA	108	2	0	0	2	8	0	0	10
Biltmore Medical Mall 2222 E Highland Ave, Phoenix, AZ, 85016	93	4	0	0	0	0	4	0	4
Prospect Tustin I 14591 Newport Avenue, Tustin, CA	14	0	0	0	1	1	0	0	2
Totals (3 locations)	215	6	0	0	3	9	4	0	16

All Buildings · 2026 program year

All 1198

No issues 0

Issues 2

Report pending 0

In Progress 8

Not completed 1188

Not linked 16

Export CSV

Building	Location	Scan Status	Findings	Repair Status	Report	
Prospect Tustin I	14591 Newport Avenue, Tustin, CA	Scan Complete	2	Repair Quoted	View quote	View report
Prospect Tustin II	14642 Newport Avenue, Tustin, ...	Scan Complete	10	Repair Quoted	View quote	View report

FINDING → FIX. SCAN COMPLETE, REPAIR QUOTED – VIEW QUOTE AND VIEW REPORT RIGHT ON THE ROW.

THE REPAIR PROPOSAL, RIGHT WHERE THE FINDING LIVES



Dashboard

Projects

Jobs

Work Orders

Material Orders

Locations

IR Summary

Work Order Report

Customer Access

Medical Facility

IR Thermographic Program Summary

3 Locations · Reporting Type: Anomaly · As of September 29, 2026

All IR Reports

Location	Full	Partial
Prospect Tustin II 14642 Newport Avenue, Tustin, CA	108	
Biltmore Medical Mall 2222 E Highland Ave, Phoenix, AZ, 85016	93	
Prospect Tustin I 14591 Newport Avenue, Tustin, CA	14	
Totals (3 locations)	215	

All Buildings · 2026 program year

2 buildings

Export CSV

Building	Location	Score
Prospect Tustin I	14591 Newport Avenue, Tustin, CA	5
Prospect Tustin II	14642 Newport Avenue, Tustin, ...	5

Deliverables - 3279004

View on work orders

Browse all files

FSG Proposal - . Facility 1(2).pdf

FSG Proposal - ... Facility 1(3).pdf

FSG Proposal - . Facility 1.pdf

FSG Proposal - .. Facility 1(2).pdf

PDF · 84.74 KB · Sep 9, 2026, 4:26 PM

1 / 3

82%

Summarize



Facility Solutions Group

Facility Solutions Group

4401 West Gate Blvd, Ste 310

Austin, TX 78745

PROPOSAL

Proposal #: 3279004

Customer #: 752694

Print Date: 2026-07-20

ISSUED TO

Medical Facility Group

Attn: Accounts Payable

Attn: Accounts Payable

Toledo, OH 43615

SERVICE SITE

PROSPECT TUSTIN 1

14591 NEWPORT AVE.

Tustin, CA 92780

Customer PO#: NEEDS PO

PROPOSED WORK

FSG respectfully submits the following proposal for your consideration and approval.

Scope Of Work:

IRSCAN

Discovery:

Survey was done on WO 3259098. Issues that were identified are:

- 1) Panel A in the main electrical room high temp connections.
- 2) Panel C in level 1 electrical room high temp connections.

Proposal:

THE QUOTE, RIGHT THERE. PROPOSALS OPEN INSIDE THE DASHBOARD, TIED TO THE WORK ORDER AND THE SITE.

THE FULL REPORT. STORED WITH THE SITE, FOREVER.



Dashboard

Projects

Jobs

Work Orders

Material Orders

Locations

IR Summary

Work Order Report

Customer Access

Medical Facility

IR Thermographic Program Summary

3 Locations · Reporting Type: Anomaly · As of September 29, 2026

All IR Reports

Location	Full	Parti
Prospect Tustin II 14642 Newport Avenue, Tustin, CA	108	
Biltmore Medical Mall 2222 E Highland Ave, Phoenix, AZ, 85016	93	
Prospect Tustin I 14591 Newport Avenue, Tustin, CA	14	
Totals (3 locations)	215	

All Buildings · 2026 program

year

2 buildings

Export CSV

Building	Location	Sc
Prospect Tustin I	14591 Newport Avenue, Tustin, CA	S
Prospect Tustin II	14642 Newport Avenue, Tustin, ...	S

Deliverables - 3259104

Medical Facility Infrared Report (07-08-2...

Browse all files

Open report

2 / 119

82%

Summarize

Overview

The project, commonly known as an Infrared Thermographic Inspection, is typically a passive collection of thermal images (thermograms) of a system's components with an Infrared Camera. The Infrared Camera used in this scan was a FLIR model E76. The components are classified as whether they operate at an acceptable thermal condition, require scheduled preventative maintenance, or immediate maintenance is needed to prevent further damage.

The inspection encompassed the electrical distribution system and electrical equipment throughout the facilities.

Electrical components captured may include any of the following or are outlined by the Job Proposal:

- Low Voltage Switchgear, switchboard, panelboard bus bar connections
- Low Voltage Switchgear, switchboard, panelboard main circuit breakers
- Low Voltage Switchgear, switchboard, panelboard branch circuit breakers
- Backup generators, automated transfer switches and controls (if energized)
- Motor control equipment
- Transformer line/load side elbow terminators (when accessible)
- Line/load side conductor lug connection areas
- Line/load side switches and fuse clip/knife points of disconnect
- Control panels and cabinets
- Motors (>50HP)
- Electrical storage devices (batteries)
- Overhead busway (bus duct) terminal box and switches (when accessible)
- UPS connections, breakers, bypasses, rectifiers, and inverters (when accessible)

Infrared Thermographic Inspection Summary

This section provides a brief synopsis of the inspection findings. Further explanation of inspection findings and recommendations for maintenance can be found in the subsequent sections of this report.

Thermogram Evaluation Preview

The inspection indicates 10 total components were observed and classified by criteria provided through Section 9 and Table 100.18 of ANSI/NETA Maintenance Testing Specifications (MTS).

The operating temperature of observed equipment is compared between temperatures of ambient air and/or between similar components under similar loading. The components reviewed indicated 8 minor deficiencies and 2 Important deficiencies according to Table 100.18 from the ANSI/NETA MTS. Component deficiency results will be represented by the following criteria:

Minor Deficiency – Monitor conditions and watch for increase in temperature.

Important Deficiency – Attention needed when next scheduled for service.

Serious Deficiency – Need to schedule maintenance soon.

Critical Deficiency – Emergency repairs needed.

COMPLETE FINDINGS. THE FULL THERMOGRAPHIC REPORT – EVERY PAGE, EVERY IMAGE, ONE CLICK FROM THE FINDING.

REPORTED TO YOU – AND ANYONE WHO ASKS

ON YOUR PHONE. ON YOUR LAPTOP. EXPORT TO ANYONE.

A complete real-time dashboard of your whole portfolio. When someone needs proof, you're one export away — no digging through binders, no calling three vendors for last year's report.

Your team

Your boss

Your board

The safety office

The fire marshal

The city official

The real-estate buyer who needs it for the bank

Reports, details, pricing, and findings – all in one place, for life. Sell a building in five years? The full maintenance history goes with it.

WHAT IF

TWO WAYS THIS YEAR CAN GO

WITHOUT A PROGRAM

- Stale arc flash studies and expired labels
- Failures found by outage, not inspection
- Emergency service calls at emergency prices
- Scrambling when the auditor or marshal shows up

WITH FSG

- Current studies, labels, and PPE matrix at every site
- Issues caught while equipment still runs normally
- Planned repairs on your budget and schedule
- Every record one click away — for anyone who asks

SEND US YOUR FACILITY LIST. WE'LL TAKE IT FROM THERE.

Call **(866) 865-7553** · **fsg.com**

FSG Engineering Services — Protecting People. Powering Performance.