


Scan Data Analysis

Generated: 1/3/2026, 11:35:19 PM


Artifacts: 2124

Summary Analysis


Section Types



Feature Prevalence




Capture Errors




Object Analysis

Object Distribution




Door Open/Closed




 Closed  Open

Chair Arm Type




 Existing  Missing

Chair Back Type




 Existing  Missing

Chair Base Type




 Four  Star  Unidentified

Chair Type




 Dining  Stool  Swivel
 Unidentified

Sofa Type




 Single Seat

Storage Type




 Cabinet  Shelf

Table Shape Type




 Circular  Rectangular
 Unidentified

Table Type




 Unidentified


Number of Sinks




Vanity Type





Tub Length Distribution




Vanity Length Distribution



Floor Analysis




Floor Aspect Ratio




Wall Analysis


Wall Heights




Wall Widths




Wall Areas




Wall Aspect Ratio




Walls with Windows






Walls with Doors




Walls with Openings



Window Analysis




Window Aspect Ratio




Door Analysis


Door Heights




Door Widths



Door Areas




Door Aspect Ratio




Opening Analysis


Opening Heights



Opening Widths



Opening Areas



Opening Aspect Ratio

