

Overview

## REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT



As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)

**Client Address** 

Client Ref				Stourbridge Turning & Grinding Holdings Rufford Road					
Description	Lifting Accessories/Single Leg Chain Sling				Stourbridge West Midlands DY9 7NG				
Type Of Inspection	6 Months				Report ID         54052         Page         1/1				
Equipment Information									
Location				Works Bay 2 barreler	Inspected At				
I.S.I. Equipment Number				124194281	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands				
Date Of Manufacture									
Serial Mark / Number				0924					
SWL(s) For The Configuration Examined				5.4 tonne					
Inspection Report									
A - Defects Requiring Immediate Rectification:			No	None					
B - Defects Requiring rectification within a specified time period:			No	None					
C - Other defects:			No	None					
D - Observations:			None						
General Comments									
Serviceable									
Declaration									
I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.									
<b>Report Date</b> 08/04/202		4		John Keber	John Keber Al				
-		08/10/2024	4		JU				



**Last Inspection Date** 

Not Known

Industrial Safety Inspections Ltd Tel: 22-23 Amber Business Village Amington Em:

Amington Tamworth Staffordshire B77 4RP

Surveyor

+44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com