

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)



Overview		Client Address			
Client Ref	Amington Engineering	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Lifting Attachments/Working Platform Attachment				
Type Of Inspection	6 Months				
		Report ID	54049	Page	1/2

Equipment Information		
Location	Works	Inspected At
I.S.I. Equipment Number	10233540	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands
Date Of Manufacture	1996	
Serial Mark / Number	15092 AFA-P1	
SWL(s) For The Configuration Examined	500kg / 2 persons + tools	

Inspection Report	
A - Defects Requiring Immediate Rectification:	None
B - Defects Requiring rectification within a specified time period:	None
C - Other defects:	1) Distortion to rear upper guard locking brackets - to rectify
D - Observations:	1) Minimum truck capacity: 1000kg @ 600mm ctrs

General Comments
Inspection carried out with minor defects

Declaration
I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)



Overview		Client Address			
Client Ref	Amington Engineering	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Lifting Attachments/Working Platform Attachment				
Type Of Inspection	6 Months				
		Report ID	54049	Page	2/2

Report Date	08/04/2024
Next Inspection Date	08/10/2024
Last Inspection Date	24/11/2023

John Keber	
Surveyor	