



Overview				Site
Inspect N	52946	Page:	1/1	<div>Rochdale DO</div> <div>AINSWORTH STREET</div> <div>ROCHDALE</div> <div>OL16 5QX</div>
Job No	14033			
Customer	AECOM			
Contact	Anth Warren	Date	02/04/2024	
Tel	07553 196353			

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
124193481	Door Automatic Pedestrian		0000000000000092

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
-----------------------------------------------------	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments

None

Engineer

Liam Weeder

L.W