



| Overview  |              |       |            | Site   |
|-----------|--------------|-------|------------|--|
| Inspect N | 52941        | Page: | 1/1        | <div>Rochdale DO</div> <div>AINSWORTH STREET</div> <div>ROCHDALE</div> <div>OL16 5QX</div> |
| Job No    | 14033        |       |            |  |
| Customer  | AECOM        |       |            |  |
| Contact   | Anth Warren  | Date  | 02/04/2024 |  |
| Tel       | 07553 196353 |       |            |  |

### Pass

| ISI Equipment No | Make / Model    | Serial No | Client ID  |
|------------------|-----------------|-----------|------------|
| 124193483        | Barrier Traffic |           | 0000212019 |

#### Asset Photograph

|   |             |
|---|-------------|
| Capture photograph of Asset, including asset number | See Photo 1 |
|---|-------------|

#### Hazard Priority and Findings

|  |                                   |
|--|-----------------------------------|
| Intolerable - Defects requiring immediate action               | None                              |
| Substantial - Defects requiring attention within a time period | None                              |
| Moderate - Other defects requiring attention                   | asset number to be clearly marked |
| Tolerable - Observations                                       | None                              |



#### General Comments

None

#### Engineer

Liam Weeder

L.W