

# REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)



Overview		Client Address			
Client Ref	Caterpillar DP25N	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Fork Lift & Pallet Trucks/Counter Balance Fork Lift Truck				
Type Of Inspection	6 Months				
		Report ID	54067	Page	1/2

Equipment Information		
Location	Works	Inspected At
I.S.I. Equipment Number	10233523	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands
Date Of Manufacture	2004	
Serial Mark / Number	ET18C 50944	
SWL(s) For The Configuration Examined	2300 kg @ 500 mm ctrs. Maximum lift: 4300 mm	

Inspection Report	
A - Defects Requiring Immediate Rectification:	None
B - Defects Requiring rectification within a specified time period:	None
C - Other defects:	None
D - Observations:	1) The carriage load chains show wear but remain serviceable. 2) The mast load chains show 1.5% elongation over 10 pitches but remain serviceable. 3) The load forks remain serviceable.

General Comments
Serviceable and operationally tested.

Declaration
I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.

# REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations  
(Regulation 9)



Overview		Client Address			
Client Ref	Caterpillar DP25N	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Fork Lift & Pallet Trucks/Counter Balance Fork Lift Truck				
Type Of Inspection	6 Months				
		Report ID	54067	Page	2/2

Report Date	08/04/2024
Next Inspection Date	08/10/2024
Last Inspection Date	24/11/2023

John Keber	
Surveyor	