

# REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations  
(Regulation 9)



Overview		Client Address			
Client Ref	Dini Argeo and associated shackle	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Lifting Accessories/Crane Weigh Scale				
Type Of Inspection	6 Months				
		Report ID	54062	Page	1/1

Equipment Information		
Location	Works Bay 2 barreler	Inspected At
I.S.I. Equipment Number	10233520	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands
Date Of Manufacture		
Serial Mark / Number	0100402168	
SWL(s) For The Configuration Examined	1500kg	

Inspection Report	
A - Defects Requiring Immediate Rectification:	None
B - Defects Requiring rectification within a specified time period:	None
C - Other defects:	None
D - Observations:	None

General Comments
Serviceable and operationally tested.

Declaration
I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.

Report Date	08/04/2024
Next Inspection Date	08/10/2024
Last Inspection Date	24/11/2023

John Keber

Surveyor

