



Overview				Site
Inspect N	52905	Page:	1/1	<div>OLDHAM DO</div> <div>21 HAMILTON STREET</div> <div>OLDHAM</div> <div>OL1 1AA</div>
Job No	14035			
Customer	AECOM			
Contact	Anth Warren	Date	02/04/2024	
Tel	07553 196353			

## Pass

ISI Equipment No	Make / Model	Serial No	Client ID
29032024020	Barrier Traffic	HDG106011	0000156204

### Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

### Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	bottom of barrier and stop signs damaged - rectify
Tolerable - Observations	asset number to be clearly marked



### General Comments

None

### Engineer

Liam Weeder