

# REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)



Overview		Client Address			
Client Ref	Raptor	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Lifting Accessories/Barrel Lifter Attachment				
Type Of Inspection	6 Months				
		Report ID	54066	Page	1/1

Equipment Information		
Location	Tackle board bay 3	Inspected At
I.S.I. Equipment Number	10233496	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands
Date Of Manufacture		
Serial Mark / Number	DN500	
SWL(s) For The Configuration Examined	500kg	

Inspection Report	
A - Defects Requiring Immediate Rectification:	None
B - Defects Requiring rectification within a specified time period:	None
C - Other defects:	None
D - Observations:	None

General Comments
Serviceable

Declaration
I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.

Report Date	08/04/2024
Next Inspection Date	08/10/2024
Last Inspection Date	24/11/2023

John Keber

Surveyor

