



Overview				Site
Inspect N	53091	Page:	1/1	STAFFORD DO NEWPORT ROAD STAFFORD ST16 1AA
Job No	14058			
Customer	AECOM			
Contact	Anth Warren	Date	03/04/2024	
Tel	07553 196353			

Pass


ISI Equipment No	Make / Model	Serial No	Client ID
RM230224186	Door Manual		0000084991

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	cardboard cable tied to gate - recommend removing



General Comments

None

Engineer

Liam Weeder

L. W.