



Overview				Site
Inspect N	52943	Page:	1/2	Rochdale DO AINSWORTH STREET ROCHDALE OL16 5QX
Job No	14033			
Customer	AECOM			
Contact	Anth Warren	Date	02/04/2024	
Tel	07553 196353			

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
124193482	Lift Goods & Passenger	78NW5491	0000212115

Asset Photograph

Capture photograph of Asset, including asset number	See Photos 1 & 2
---	------------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments	General
None	None



Engineer

Liam Weeder

L. W.

Comments