



Overview				Site	
Inspect N	53096	Page:	1/2		
Job No	14058				
Customer	AECOM				
Contact	Anth Warren	Date	03/04/2024		
Tel	07553 196353				
				STAFFORD DO	
				NEWPORT ROAD	
				STAFFORD	
				ST16 1AA	

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
RM230224182	Door Manual		0000084966

Asset Photograph

Capture photograph of Asset, including asset number	See Photos 1 & 2
---	------------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	asset number to be clearly marked
Tolerable - Observations	None



General Comments	General
None	None

Engineer

Liam Weeder

L. W.

Comments