



Overview				Site	
Inspect N	53082	Page:	1/1	STAFFORD DO NEWPORT ROAD STAFFORD ST16 1AA	
Job No	14058				
Customer	AECOM				
Contact	Anth Warren	Date	03/04/2024		
Tel	07553 196353				

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
RM230224321	Barrier Traffic		0000698827

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments

None

Engineer

Liam Weeder

L.W