



Overview				Site	
Inspect N	53093	Page:	1/1		
Job No	14058				
Customer	AECOM				
Contact	Anth Warren	Date	03/04/2024		
Tel	07553 196353				
				STAFFORD DO	
				NEWPORT ROAD	
				STAFFORD	
				ST16 1AA	

Pass


ISI Equipment No	Make / Model	Serial No	Client ID
RM230224178	Door Manual		0000084956

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	asset number to be clearly marked
Tolerable - Observations	None



General Comments

None

Engineer

Liam Weeder

L.W