



Working in Waters of the State Daily Inspection

Project		Site	
Microsoft RNO18 Main Campus		Western Drainage (Culvert at station 12+50)	
Date	Time	Initials	
2026-09-28	07:45	GRX	

Daily Checks

Is there water in the waterway?	Yes
Comment: Low flow, about 4 inches	
Daily Vehicle Inspection	Pass
BMPs Visual Inspection	Fail
Comment: Wattle torn at north end, replaced	
Visible sheen/plume?	N/A

Equipment in use in and around waterway today

CAT 320 excavator, water truck

Site Photos

Looking upstream