

Gas Service/Breakdown Record

Certificate Ref.

1 Church Terrace

Certificate No 1 Church Terrace

Installation Details

Installation Address: Daniel Meggitt
1 Church Terrace
Cublington
Leamington Spa
Postcode: CV327JX

Client Details

Client Address: Daniel Meggitt
3 Church Terrace
Cublington, Leamington Spa
Postcode: CV327JX

Appliance Details

CO/CO2 Ratio:

Service:

Breakdown: N/A

CO2 Reading:

CO Reading: ppm

Boiler Make: Boiler Model: Boiler Serial No:
Appliance Make: Appliance Model: Appliance Serial No:

Preliminary Checks	Satisfactory	YES	NO	NA
Flue:Atmospheric/Fan assisted/Fan Dilution				
Ventilation Size/H-L				
Water/Fuel - Sound				
Electrically Fused				
Correct Valving Arrangement				
Isolation Available - Electrical/Fuel (Within 1 metre)				
Boiler/Plant room Clean & Clear				
Service Checks	Satisfactory	YES	NO	NA
Heat Exchanger				
Ignition				
Gas Valve				
Fan				NA
Safety Device				NA
Control Box				
Burner & Pilot				
Fuel Pressure & Type				
Service Operations	Satisfactory	YES	NO	NA
Burner Washed & Clean				
Pilot Assembly Cleaned & Adjusted				
Ignition System Cleaned & Adjusted				
Burner Fan & Airways Cleaned				
Heat Exchanger/Flueways Clean & Clear				NA
Fuel & Electrical Supply Connected & Sound				
Interlocks in Place				

Additional Notes

Spares Required

Engineers Details

Trading Title: Coventry Gas Services Ltd
47 Alspath Road
Meriden
Postcode: CV7 7LU

Gas Safe Number: 927997
Gas ID Number: 5545563
Telephone Number: 07961768920
Time of Arrival: 11:59 am
Time of Departure: 11:59 am

Report Issued By Name: Andrew King-Page
Signature: 
Date: Tue-29-Aug-2023
Report Received By Name:
Signature:
Date: Tue-29-Aug-2023