

Gas Service/Breakdown Record

Certificate Ref.

2 Church Terrace

Certificate No 2 Church Terrace

Installation Details

Installation Address:

Daniel Meggitt
3 Church Terrace
Cublington, Leamington Spa

Postcode: CV327JX

Client Details

Client Address:

Daniel Meggitt
3 Church Terrace
Cublington, Leamington Spa

Postcode: CV327JX

Appliance Details

CO/CO2 Ratio:

Service:

Breakdown: N/A

CO2 Reading:

%

CO Reading:

ppm

Boiler Make:

Boiler Model:

Boiler Serial No:

Appliance Make:

Appliance Model:

Appliance Serial No:

Preliminary Checks

Satisfactory

YES

NO

NA

Flue:Atmospheric/Fan assisted/Fan Dilution

Ventilation Size/H-L

Water/Fuel - Sound

Electrically Fused

Correct Valving Arrangement

Isolation Available - Electrical/Fuel (Within 1 metre)

Boiler/Plant room Clean & Clear

Service Checks

Satisfactory

Heat Exchanger

Ignition

Gas Valve

Fan

NA

Safety Device

NA

Control Box

Burner & Pilot

Fuel Pressure & Type

Service Operations

Satisfactory

Burner Washed & Clean

Pilot Assembly Cleaned & Adjusted

Ignition System Cleaned & Adjusted

Burner Fan & Airways Cleaned

Heat Exchanger/Flueways Clean & Clear

NA

Fuel & Electrical Supply Connected & Sound

Interlocks in Place

Additional Notes

Spares Required

Engineers Details

Trading Title:

Coventry Gas Services Ltd
47 Alspath Road
Meriden

Postcode: CV7 7LU

Gas Safe Number

927997

Time of Arrival:

09:09 am

Gas ID Number

5545563

Time of Departure:

09:09 am

Telephone Number

07961768920

Report Issued By Name:

Andrew King-Page

Signature:



Date:

Tue-29-Aug-2023

Report Received By Name:

Signature:

Date:

Tue-29-Aug-2023