

Gas Service/Breakdown Record

Certificate Ref.

23 shelbourne road

Certificate No 23 shelbourne road

Installation Details

Installation
Address:

Ed silk
23 shelbourne road
Stratford Upon Avon

Postcode: CV37 9JR

Client Details

Client
Address:

Ed silk
23 shelbourne road
Stratford Upon Avon

Postcode: CV37 9JR

Appliance Details

CO/CO2
Ratio:

Service:

Breakdown:

N/A

CO2
Reading:

%

CO Reading:

ppm

Boiler Make:

Boiler Model:

Boiler Serial No:

Appliance Make:

Appliance Model:

Appliance Serial No:

Preliminary Checks

Satisfactory

YES

NO

NA

Flue:Atmospheric/Fan assisted/Fan Dilution

Ventilation Size/H-L

Water/Fuel - Sound

Electrically Fused

Correct Valving Arrangement

Isolation Available - Electrical/Fuel (Within 1 metre)

Boiler/Plant room Clean & Clear

Service Checks

Satisfactory

Heat Exchanger

Ignition

Gas Valve

Fan

NA

Safety Device

NA

Control Box

Burner & Pilot

Fuel Pressure & Type

Service Operations

Satisfactory

Burner Washed & Clean

Pilot Assembly Cleaned & Adjusted

Ignition System Cleaned & Adjusted

Burner Fan & Airways Cleaned

Heat Exchanger/Flueways Clean & Clear

NA

Fuel & Electrical Supply Connected & Sound

Interlocks in Place

Additional Notes

Spares Required

Engineers Details

Trading Title:

Coventry Gas Ltd
47 Alspath Road
Meriden

Postcode: CV7 7LU

Gas Safe Number

526645

Time of
Arrival:

05:36 pm

Gas ID Number

4464997

Time of

Telephone Number

07961768920

Departure:

05:36 pm

Report Issued By

Name: Andrew King-Page

Signature:

Date:

Thu-30-Mar-2023

Report Received By

Name:

Signature:

Date:

Thu-30-Mar-2023