

Gas Service/Breakdown Record

Certificate Ref.

71 Welby Road Birmingham B28 8H

Certificate No 71 Welby Road Birmir

Installation Details

Installation Address: Daniel Hall
71 Welby Road
Birmingham

Postcode: B28 8HP

Client Details

Client Address: Daniel Hall
71 Welby Road
Birmingham

Postcode: B28 8HP

Appliance Details

CO/CO2 Ratio:

0.0006

Service:

YES

Breakdown:

N/A

CO2 Reading:

9.5 %

CO Reading:

50 ppm

Boiler Make: Baxi

Boiler Model: Megaflo 2 System 12

Boiler Serial No:

Appliance Make:

Appliance Model:

Appliance Serial No:

Preliminary Checks

Satisfactory

YES

NO

NA

Flue:Atmospheric/Fan assisted/Fan Dilution	YES		
Ventilation Size/H-L	YES		
Water/Fuel - Sound	YES		
Electrically Fused	YES		
Correct Valving Arrangement	YES		
Isolation Available - Electrical/Fuel (Within 1 metre)	YES		
Boiler/Plant room Clean & Clear	YES		

Service Checks

Satisfactory

Heat Exchanger			
Ignition			
Gas Valve			
Fan			NA
Safety Device			NA
Control Box			
Burner & Pilot			
Fuel Pressure & Type	YES		

Service Operations

Satisfactory

Burner Washed & Clean			
Pilot Assembly Cleaned & Adjusted			
Ignition System Cleaned & Adjusted			
Burner Fan & Airways Cleaned			
Heat Exchanger/Flueways Clean & Clear			NA
Fuel & Electrical Supply Connected & Sound	YES		
Interlocks in Place			

Additional Notes

serviced boiler and unvented cylinder

Spares Required

none

Engineers Details

Trading Title: Coventry Gas Ltd
47 Alspath Road
Meriden

Postcode: CV7 7LU

Gas Safe Number

526645

Time of Arrival:

01:12 pm

Gas ID Number

4464997

Time of

Telephone Number

07961768920

Departure:

01:12 pm

Report Issued By Name: Andrew King-Page

Signature:

Date: Fri-13-Jan-2023

Report Received By Name: Andrew King-Page

Signature:

Date: Fri-13-Jan-2023