

Gas Service/Breakdown Record

Certificate Ref.

1 Manor Orchard

Certificate No 1 Manor Orchard

Installation Details

Installation Address: Phil Harbury
1 Manor Orchard
Harbury

Postcode: CV33 9LZ

Client Details

Client Address: Phil Harbury
1 Manor Orchard
Harbury

Postcode: CV33 9LZ

Appliance Details

CO/CO2 Ratio:

N/A

Service:

YES

Breakdown:

N/A

CO2 Reading:

%

CO Reading:

ppm

Boiler Make:

Baxi

Boiler Model:

Bermuda 401

Boiler Serial No:

Appliance Make:

Appliance Model:

Appliance Serial No:

Preliminary Checks

Satisfactory

YES

NO

NA

Flue:Atmospheric/Fan assisted/Fan Dilution

Ventilation Size/H-L

YES

Water/Fuel - Sound

YES

Electrically Fused

YES

Correct Valving Arrangement

YES

Isolation Available - Electrical/Fuel (Within 1 metre)

YES

Boiler/Plant room Clean & Clear

YES

Service Checks

Satisfactory

Heat Exchanger

YES

Ignition

YES

Gas Valve

YES

Fan

NA

Safety Device

YES

Control Box

YES

Burner & Pilot

YES

Fuel Pressure & Type

YES

Service Operations

Satisfactory

Burner Washed & Clean

YES

Pilot Assembly Cleaned & Adjusted

YES

Ignition System Cleaned & Adjusted

YES

Burner Fan & Airways Cleaned

YES

Heat Exchanger/Flueways Clean & Clear

YES

Fuel & Electrical Supply Connected & Sound

YES

Interlocks in Place

Additional Notes

back boiler service, burner pressure 9,5mb, gas rate 8.38kw

Spares Required

none

Engineers Details

Trading Title:

Coventry Gas Ltd
47 Alspath Road
Meriden

Postcode: CV7 7LU

Gas Safe Number

526645

Time of Arrival:

12:22 pm

Gas ID Number

4464997

Time of

Telephone Number

07961768920

Departure:

12:22 pm

Report Issued By

Name:

Andrew King-Page

Signature:



Date:

Wed-10-Aug-2022

Report Received By

Name:

Signature:

Date:

Wed-10-Aug-2022