

Gas Service/Breakdown Record

Certificate Ref.

94 Dillotford Avenue Coventry CV3

Certificate No 94 Dillotford Avenue C

Installation Details

Installation Address: Patrick Cosgrove
94 Dillotford Avenue
Coventry
Postcode: CV3 5DU

Client Details

Client Address: Patrick Cosgrove
94 Dillotford Avenue
Coventry
Postcode: CV3 5DU

Appliance Details

CO/CO2 Ratio: Service: Breakdown: CO2 Reading: CO Reading:

Boiler Make: Boiler Model: Boiler Serial No:
Appliance Make: Appliance Model: Appliance Serial No:

Preliminary Checks	Satisfactory	YES	NO	NA
Flue:Atmospheric/Fan assisted/Fan Dilution				
Ventilation Size/H-L				
Water/Fuel - Sound				
Electrically Fused				
Correct Valving Arrangement				
Isolation Available - Electrical/Fuel (Within 1 metre)				
Boiler/Plant room Clean & Clear				
Service Checks	Satisfactory	YES	NO	NA
Heat Exchanger				
Ignition				
Gas Valve				
Fan				NA
Safety Device				NA
Control Box				
Burner & Pilot				
Fuel Pressure & Type				
Service Operations	Satisfactory	YES	NO	NA
Burner Washed & Clean				
Pilot Assembly Cleaned & Adjusted				
Ignition System Cleaned & Adjusted				
Burner Fan & Airways Cleaned				
Heat Exchanger/Flueways Clean & Clear				NA
Fuel & Electrical Supply Connected & Sound				
Interlocks in Place				

Additional Notes

Spares Required

Engineers Details

Trading Title: Coventry Gas Ltd
47 Alspath Road
Meriden
Postcode: CV7 7LU

Gas Safe Number: 526645 Time of Arrival: 04:23 pm
Gas ID Number: 4464997 Time of Departure: 04:23 pm
Telephone Number: 07961768920

Report Issued By Name: Andrew King-Page Signature:  Date: Wed-13-Oct-2021
Report Received By Name: Signature: Date: Wed-13-Oct-2021