

Gas Service/Breakdown Record

Certificate Ref.

7 Rock Mill Lane

Certificate No 7 Rock Mill Lane

Installation Details

Installation Address: 7 Rock Mill Lane
7 Rock Mill Lane
Leamington Spa

Postcode: CV32 6AP

Client Details

Client Address: Appledoor
5&6 Southlynn Gardens
Shipston upon Stour
Warwickshire

Postcode: CV36 4ER

Appliance Details

CO/CO2 Ratio:

N/A

Service:

YES

Breakdown:

N/A

CO2 Reading:

%

CO Reading:

ppm

Boiler Make: Potterton Boiler Model: Power max 185 Boiler Serial No:

Appliance Make: Appliance Model: Appliance Serial No:

Preliminary Checks

Satisfactory

YES

NO

NA

Flue:Atmospheric/Fan assisted/Fan Dilution	YES		
Ventilation Size/H-L	YES		
Water/Fuel - Sound	YES		
Electrically Fused	YES		
Correct Valving Arrangement	YES		
Isolation Available - Electrical/Fuel (Within 1 metre)	YES		
Boiler/Plant room Clean & Clear	YES		

Service Checks

Satisfactory

Heat Exchanger	YES		
Ignition	YES		
Gas Valve	YES		
Fan	YES		
Safety Device	YES		
Control Box	YES		
Burner & Pilot	YES		
Fuel Pressure & Type	YES		

Service Operations

Satisfactory

Burner Washed & Clean			
Pilot Assembly Cleaned & Adjusted			
Ignition System Cleaned & Adjusted			
Burner Fan & Airways Cleaned			
Heat Exchanger/Flueways Clean & Clear			NA
Fuel & Electrical Supply Connected & Sound	YES		
Interlocks in Place			

Additional Notes

boiler service, boiler is showing signs of age related decay.

Spares Required

New seals

Engineers Details

Trading Title: Coventry Gas Ltd
47 Alspath Road
Meriden

Postcode: CV7 7LU

Gas Safe Number: 526645 Time of Arrival: 10:32 am
Gas ID Number: 4464997
Telephone Number: 07961768920 Time of Departure: 10:32 am

Report Issued By Name: Andrew King-Page Signature: Date: Fri-12-Mar-2021

Report Received By Name: Signature: Date: Fri-12-Mar-2021