



Gas Service/Maintenance Check List

This form should not be used as a Landlord Gas Safety Record

Certificate Reference:

47 Wetherby Way-Mr M Baines-25Jul2019

Certificate No: 47 Wetherby Way

Installation Details

Installation Address:

47 Wetherby way
47 Wetherby way
Stratford Upon Avon

Postcode: CV37 9LU

Client Details

Client Address:

Mr M Baines
53 Wetherby Way
Stratford Upon Avon

Postcode: CV37 9LU

Appliance Details

Service: ☐ YES Maintenance: ☐ YES Gas Tightness Carried Out?: ☐ YES Gas Tightness Test: ☐ YES CO/CO2 ratio: CO2 reading: CO reading:

Appliance Location: Type: Make: Model:

Appliance Checks

	YES	NO	N/A	Remedial Action/Nature of Defect
Burner/Injectors	YES			
Heat Exchanger	YES			
Ignition	YES			
Electrics	YES			
Controls	YES			
Gas/Water Leaks	YES			
Gas Connections	YES			
Seals (appliance case etc)	YES			
Gas Pipework	YES			
Fan(s)	YES			
Fireplace opening/void			NA	
Closure plate			NA	
Flame Picture			NA	
Location	YES			
Stability	YES			
Return air/plenum			NA	

Safety Checks

	YES	NO	N/A	Remedial Action/Nature of Defect
Ventilation	YES			
Flue Termination	YES			
Flue Flow Test			NA	
Spillage Test			NA	
Inlet Working Pressure	YES			
Safety device (s)	YES			
Burner Pressure			NA	

Findings

Is Appliance/installation safe to use? If NO, has a warning notice been issued and a warning label attached?

Does the Installation conform to the requirements of manufacturer's instructions/installation standards?

The following remedial work is required:

Engineers Details

Trading Title:
47 Alspath Road
Meriden
Postcode: CV7 7LU

Gas Safe Number:
Gas ID Number:
Telephone Number:

Report Issued By Name: Signature:
Date:

Report Received By Name: Signature:
Date: