



Gas Service/Maintenance Check List

This form should not be used as a Landlord Gas Safety Record

Certificate Reference:

Ser0002

Certificate No: 000002

Installation Details

Installation
Address:

Sean Clarkson
10 Granada Way
Leamington Spa

Postcode: CV31 1PW

Client Details

Client
Address:

Sean Clarkson
10 Granada Way
Leamington Spa

Postcode: CV31 1PW

Appliance Details

Service:	YES	Maintenance:	NA	Gas Tightness Carried Out?:	NO	Gas Tightness Test:	NA	CO/CO2 ratio:	0.0006	CO2 reading:	9.48	CO reading:	53
Appliance Location:				Type:	Combi Boiler		Make:	Vaillant		Model:	Ecofit Sustain 830		

Appliance Checks

	YES	NO	N/A	Remedial Action/Nature of Defect
Burner/Injectors	YES			
Heat Exchanger	YES			
Ignition	YES			
Electrics	YES			
Controls	YES			
Gas/Water Leaks	YES			
Gas Connections	YES			
Seals (appliance case etc)	YES			
Gas Pipework			NA	
Fan(s)			NA	
Fireplace opening/void			NA	
Closure plate			NA	
Flame Picture			NA	
Location			NA	
Stability			NA	
Return air/plenum			NA	

Safety Checks

	YES	NO	N/A	Remedial Action/Nature of Defect
Ventilation	YES			
Flue Termination	YES			
Flue Flow Test			NA	
Spillage Test			NA	
Inlet Working Pressure			NA	
Safety device (s)	YES			
Burner Pressure			NA	

Findings

Is Appliance/installation safe to use?	YES	If NO, has a warning notice been issued and a warning label attached?	NA
Does the Installation conform to the requirements of manufacturer's instructions/installation standards?	NA		

The following remedial work is required:

--	--

Engineers Details

Trading Title:	Coventry Gas Services 47 Alspath Road Meriden	Gas Safe Number:	526645		
		Gas ID Number:	4464997		
	Postcode: CV7 7LU	Telephone Number:	07961768920		
Report Issued By	Name: Andrew King-Page	Signature:		Date:	Thu-04-Apr-2019
Report Received By	Name: Andrew King-Page	Signature:		Date:	Thu-04-Apr-2019