



Gas Service/Maintenance Check List

This form should not be used as a Landlord Gas Safety Record

Certificate Reference:

203 Cubbington Road

Certificate No: 203 Cubbington

Installation Details

Installation Address: Lak Atwal
13 Summerton Rd
Leamington Spa
Whitnash
Postcode: CV31 3AE

Client Details

Client Address: Lak Atwal
13 Summerton Rd
Leamington Spa
Whitnash
Postcode: CV31 3AE

Appliance Details

Service: YES Maintenance: NA Gas Tightness Carried Out?: NA Gas Tightness Test: NA CO/CO2 ratio: CO2 reading: CO reading:
Appliance Location: Type: Combi Boiler Make: Worcester Model: Greenstar 25i Erp

Appliance Checks

	YES	NO	N/A	Remedial Action/Nature of Defect
Burner/Injectors	YES			
Heat Exchanger	YES			
Ignition	YES			
Electrics	YES			
Controls	YES			
Gas/Water Leaks	YES			
Gas Connections	YES			
Seals (appliance case etc)	YES			
Gas Pipework	YES			
Fan(s)	YES			
Fireplace opening/void			NA	
Closure plate			NA	
Flame Picture			NA	
Location	YES			
Stability	YES			
Return air/plenum			NA	

Safety Checks

	YES	NO	N/A	Remedial Action/Nature of Defect
Ventilation	YES			
Flue Termination	YES			
Flue Flow Test			NA	
Spillage Test			NA	
Inlet Working Pressure	YES			
Safety device (s)	YES			
Burner Pressure			NA	

Findings

Is Appliance/installation safe to use? YES If NO, has a warning notice been issued and a warning label attached? NA

Does the Installation conform to the requirements of manufacturer's instructions/installation standards? YES

The following remedial work is required:

Engineers Details

Trading Title: Coventry Gas Services
47 Alspath Road
Meriden
Postcode: CV7 7LU
Gas Safe Number: 526645
Gas ID Number: 4464997
Telephone Number: 07961768920

Report Issued By Name: Andrew King-Page Signature: Date: Fri-08-Feb-2019
Report Received By Name: Andrew King-Page Signature: Date: Fri-08-Feb-2019