

Gas Service/Breakdown Record

Certificate Ref.

27 Borrowdale drive cv32 6ny

Certificate No 27 Borrowdale drive c

Installation Details

Installation
Address:

Micheal Edwards
27 Borrowdale drive
Leamington Spa

Postcode: CV32 6NY

Client Details

Client
Address:

Micheal Edwards
27 Borrowdale drive
Leamington Spa

Postcode: CV32 6NY

Appliance Details

CO/CO2
Ratio:

0.0006

Service:

YES

Breakdown:

CO2

Reading:

8.5 %

CO Reading:

48 ppm

Boiler Make:

Vaillant

Boiler Model:

Ecotec Plus 630

Boiler Serial No:

Appliance Make:

Appliance Model:

Appliance Serial No:

Preliminary Checks

Satisfactory

YES

NO

NA

Flue:Atmospheric/Fan assisted/Fan Dilution

YES

Ventilation Size/H-L

YES

Water/Fuel - Sound

YES

Electrically Fused

YES

Correct Valving Arrangement

YES

Isolation Available - Electrical/Fuel (Within 1 metre)

YES

Boiler/Plant room Clean & Clear

YES

Service Checks

Satisfactory

Heat Exchanger

YES

Ignition

YES

Gas Valve

YES

Fan

YES

Safety Device

YES

Control Box

YES

Burner & Pilot

YES

Fuel Pressure & Type

YES

Service Operations

Satisfactory

Burner Washed & Clean

Pilot Assembly Cleaned & Adjusted

Ignition System Cleaned & Adjusted

Burner Fan & Airways Cleaned

Heat Exchanger/Flueways Clean & Clear

NA

Fuel & Electrical Supply Connected & Sound

YES

Interlocks in Place

Additional Notes

cleaned filter and condense trap

Spares Required

boiler has major rust at back of diverter valve, boiler is missing a seal around the pressure relief valve, boilers insulation pads are badly degraded

Engineers Details

Trading Title:

Gas Safe Number

Time of
Arrival:

Gas ID Number

Time of
Departure:

Telephone Number

Postcode:

Report Issued By

Name:

Signature:

Date:

Report Received By

Name:

Signature:

Date: