



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

9 Dudley 2024

Certificate No: 9 Dudley 2024

Engineers Details

Trading Title

Address

Post Code:

Gas Safe No:

Telephone No:

Installation Details

Installation Address

9 Dudley House ☐ Grafton Close ☐ Kenilworth ☐ CV8 1
9 Dudley House ☐ Grafton Close ☐ Kenilworth ☐ CV8 1
9 Dudley House ☐ Grafton Close ☐ Kenilworth ☐ CV8 1
9 Dudley House ☐ Grafton Close ☐ Kenilworth ☐ CV8 1

Post Code:

Telephone No:

Client Details

Client Address

Richard Clifford
28 The Wardens, Kenilworth CV8 2UH, UK
Kenilworth
UK

Post Code: CV8 2UH

Telephone No:

447802210452

Appliance Details

Inspection Details

	Location	Appliance Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	Flue Type (OF/RS/FL)	Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure (mbar) or Heat Input (kW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Kitchen	Central Heating Boiler	Potterton	PROMAX SL15 HE PLUS	8.0	15	RS	YES	0.0002	YES	13.89 kw	YES	YES	YES	N/A	YES	YES
2	Kitchen	Hob	Bosch	Unknown	NA	NA	FL	YES	NA	YES	18 mb	YES	YES	NA	N/A	NO	YES
3																	
4																	
5																	

Faults/Notes

Remedial Work Taken

Warning Notice Fixed

1		
2		
3		
4		
5		

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

YES

Number of Appliances Tested:

2

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON OR BEFORE:

Sat-01-Nov-2025

Installation Pass:

YES

CO Alarm fitted & working?

YES

Smoke alarm fitted & working?

YES

Signatures

Report Issued By:

Name:

Signed:

Date: Fri-01-Nov-2024

Report Received By:

Name:

Signed:

Date: Fri-01-Nov-2024

Gas ID Number: