



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

46 Moseley Road 2024

Certificate No: 46 Moseley Road 2024

Engineers Details

Trading Title Coventry Gas Services Ltd

Address 47 Alspath Road
Meriden

Post Code: CV7 7LU

Gas Safe No: 927997

Telephone No: 07961768920

Installation Details

Installation Address

46 Moseley Road Kenilworth CV8 2AQ

46 Moseley Road Kenilworth CV8 2AQ

46 Moseley Road Kenilworth CV8 2AQ

46 Moseley Road Kenilworth CV8 2AQ

Post Code: CV8 2AQ

Client Details

Client Address

Mr M Burnham

C/o Leaders

1 Warwick Road

Kenilworth

Post Code: CV8 1HD

Appliance Details

Inspection Details

	Location	Appliance Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	Flue Type (OF/RS/FL)	Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure (mbar) or Heat Input (kW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Lounge	Fire	Valor Gas fire	BR 419	NA	NA	OF	YES	NA	YES	NA kw	NO	YES	YES	N/A	NO	NO
2	Kitchen	Cooker	Kenwood	Mnt2t	NA	NA	FL	NO	NA	YES	17 mb	YES	YES	NA	N/A	NO	YES
3	Kitchen	Combi Boiler	Ideal	Esprit 2	9.5	50	RS	YES	0.0005	YES	24.17 kw	YES	YES	YES	N/A	YES	YES
4																	
5																	

Faults/Notes

Remedial Work Taken

Warning Notice Fixed

1	ep bonding not before the first tee	advised landlord	NO
2	gas fire disconnected from gas with permission from the tenant	isolated gas fire from gas supply	NO
3			
4			
5			

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

YES

Number of Appliances Tested:

2

Equipotential Bonding:

NO

NEXT INSPECTION DUE ON OR BEFORE:

Mon-25-Aug-2025

Installation Pass:

YES

CO Alarm fitted & working?

YES

Smoke alarm fitted & working?

YES

Signatures

Report Issued By:

Name: Andrew King-Page

Signed:

Date: Tue-23-Jul-2024

Report Received By:

Name:

Signed:

Date: Tue-23-Jul-2024

Gas ID Number: 5545563