



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

43 Drew Crescent 2024

Certificate No: 43 Drew Crescent 2024

Engineers Details

Trading Title
Coventry Gas Services Ltd

Address
47 Alspath Road
Meriden

Post Code: CV7 7LU

Gas Safe No: 927997

Telephone No: 07961768920

Installation Details

Installation
Address

43 Drew Crescent, Kenilworth, England, CV8 1RD,
43 Drew Crescent, Kenilworth, England, CV8 1RD,
43 Drew Crescent, Kenilworth, England, CV8 1RD,
43 Drew Crescent, Kenilworth, England, CV8 1RD,

Post Code: CV8 1RD

Client Details

Client
Address

Mr Christopher Mark Tandy
C/O Leaders
31 Foregate Street Worcester WR1 1EE
31 Foregate Street Worcester WR1 1EE

Post Code: WR1 1EE

Appliance Details

Inspection Details

	Location	Appliance Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	Flue Type (OF/RS/FL)	Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(kW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Airing Cupboard	Water Heater	Ferrolli	Sky Eco F14M	NA	NA	RS	YES	NA	YES	13.45 kw	YES	YES	YES	N/A	NO	YES
2	Bed Room	Space Heater	Valor Gas fire	Brazilia F5 Beige	NA	NA	RS	YES	NA	YES	NA mb	NO	YES	YES	N/A	NO	NO
3																	
4																	
5																	

Faults/Notes

Remedial Work Taken

Warning Notice Fixed

1	space heater disconnect prior to visit	none	NO
2			
3			
4			
5			

Emergency Control Valve
Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

YES

Number of Appliances Tested:

2

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON
OR BEFORE:

Wed-01-Jul-2026

Installation Pass:

YES

CO Alarm fitted & working?

YES

Smoke alarm fitted & working?

YES

Signatures

Report Issued By:

Name: Andrew King-Page

Signed:

Date: Mon-03-Jun-2024

Report Received By:

Name:

Signed:

Date: Mon-03-Jun-2024

Gas ID Number: 5545563