



# Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

15 Chamberain Crescent Gsr 5

Certificate No: 15 Chamberain Crescent Gsr 5

## Engineers Details

Trading Title: Coventry Gas Services Ltd

Address: 47 Alspath Road  
Meriden  
Post Code: CV7 7LU

Gas Safe No: 927997 Telephone No: 07961768920

## Installation Details

Installation Address: 15 Chamberain Crescent  
15 Chamberain Crescent  
Shirley  
Solihull  
Post Code: B90 2DG

## Client Details

Client Address: Mark Dillane  
40 Langfield Road  
Knowle  
Solihull  
Post Code: B93 9PS

## Appliance Details

## Inspection Details

|   | Location | Appliance Type | Make            | Model                | CO2 Reading (%) | CO Reading (ppm) | Flue Type (OF/RS/FL) | Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only) | Combustion Analysis Reading (CO/CO2) | Landlords Appliance (YES/NO/NA) | Operating Pressure(mbar) or Heat Input(kW) | Safety Device(s) Correct Operation (YES/NO/NA) | Ventilation Provision Satisfactory (YES/NO) | Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA) | Flue Performance Test (PASS/FAIL/NA) | Appliance Serviced (YES/NO/NA) | Appliance Safe To Use (YES/NO) |
|---|----------|----------------|-----------------|----------------------|-----------------|------------------|----------------------|------------------------------------------------------------------|--------------------------------------|---------------------------------|--------------------------------------------|------------------------------------------------|---------------------------------------------|-------------------------------------------------------------------|--------------------------------------|--------------------------------|--------------------------------|
| 1 | Kitchen  | Hob            | Lamona          | Na                   | NA              | NA               | FL                   |                                                                  | NA                                   | NA                              | 19 mb                                      | YES                                            | YES                                         | NA                                                                | N/A                                  | NO                             | YES                            |
| 2 | Lounge   | Fire           | Robinson Willey | Black Beauty 4       | NA              | NA               | OF                   | YES                                                              | NA                                   | YES                             | 6.23 kw                                    | YES                                            | YES                                         | YES                                                               | PASS                                 | NO                             | YES                            |
| 3 | Kitchen  | Combi Boiler   | Intergas        | Combi Compact Hre 28 | 8.6             | 36               | RS                   | YES                                                              | 0.0004                               | YES                             | 24.18 kw                                   | YES                                            | YES                                         | YES                                                               | N/A                                  | YES                            | YES                            |
| 4 |          |                |                 |                      |                 |                  |                      |                                                                  |                                      |                                 |                                            |                                                |                                             |                                                                   |                                      |                                |                                |
| 5 |          |                |                 |                      |                 |                  |                      |                                                                  |                                      |                                 |                                            |                                                |                                             |                                                                   |                                      |                                |                                |

## Faults/Notes

## Remedial Work Taken

## Warning Notice Fixed

|   |                                                                         |                  |    |
|---|-------------------------------------------------------------------------|------------------|----|
| 1 | flue should have a 3° fall to stop dripping condense onto gas meter box | advised landlord | NO |
| 2 | flue should be sealed around outside                                    | advised landlord | NO |
| 3 |                                                                         |                  |    |
| 4 |                                                                         |                  |    |
| 5 |                                                                         |                  |    |

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

YES

Number of Appliances Tested:

2

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON OR BEFORE:

Sun-17-Nov-2024

Installation Pass:

YES

CO Alarm fitted & working?

YES

Smoke alarm fitted & working?

YES

## Signatures

Report Issued By:

Name: Andrew King-Page

Signed:

Gas ID Number: 5545563

Date: Mon-23-Oct-2023

Report Received By:

Name:

Signed:

Date: Mon-23-Oct-2023