



# Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

6 Cherry Orchard

Certificate No: 6 Cherry Orchard

## Engineers Details

Trading Title Coventry Gas Services Ltd

Address 47 Alspath Road  
Meriden

Post Code: CV7 7LU

Gas Safe No: 927997

Telephone No: 07961768920

## Installation Details

Installation Address 6 Cherry Orchard Kenilworth CV8 2SZ

6 Cherry Orchard Kenilworth CV8 2SZ

6 Cherry Orchard Kenilworth CV8 2SZ

6 Cherry Orchard Kenilworth CV8 2SZ

Post Code: CV8 2SZ

## Client Details

Client Address Mrs Erskine  
C/o Leaders

1 Warwick Road

Kenilworth

Post Code: CV8 1HD

## Appliance Details

## Inspection Details

|   | Location | Appliance Type | Make       | Model         | CO2 Reading (%) | CO Reading (ppm) | Flue Type (OF/RS/FL) | Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only) | Combustion Analysis Reading (CO/CO2) | Landlords Appliance (YES/NO/NA) | Operating Pressure (mbar) or Heat Input (kW) | Safety Device(s) Correct Operation (YES/NO/NA) | Ventilation Provision Satisfactory (YES/NO) | Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA) | Flue Performance Test (PASS/FAIL/NA) | Appliance Serviced (YES/NO/NA) | Appliance Safe To Use (YES/NO) |
|---|----------|----------------|------------|---------------|-----------------|------------------|----------------------|------------------------------------------------------------------|--------------------------------------|---------------------------------|----------------------------------------------|------------------------------------------------|---------------------------------------------|-------------------------------------------------------------------|--------------------------------------|--------------------------------|--------------------------------|
| 1 | Lounge   | Fire           | Flavel     | Emberglow     | NA              | NA               | OF                   | YES                                                              | NA                                   | YES                             | NA mb                                        | NO                                             | YES                                         | NO                                                                | FAIL                                 | NO                             | NO                             |
| 2 | Kitchen  | Hob            | Electrolux | Unknown       | NA              | NA               | FL                   | YES                                                              | NA                                   | YES                             | 20 mb                                        | YES                                            | YES                                         | NA                                                                | N/A                                  | NO                             | YES                            |
| 3 | Kitchen  | Combi Boiler   | Vaillant   | Ecotec Pro 28 | 9.5             | 95               | RS                   | YES                                                              | 0.0010                               | YES                             | 27.45 kw                                     | YES                                            | YES                                         | YES                                                               | N/A                                  | NO                             | YES                            |
| 4 |          |                |            |               |                 |                  |                      |                                                                  |                                      |                                 |                                              |                                                |                                             |                                                                   |                                      |                                |                                |
| 5 |          |                |            |               |                 |                  |                      |                                                                  |                                      |                                 |                                              |                                                |                                             |                                                                   |                                      |                                |                                |

## Faults/Notes

## Remedial Work Taken

## Warning Notice Fixed

|   |                                                               |                                                                                         |     |
|---|---------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----|
| 1 | gas fire not igniting, unable to test                         | issued warning notice, applied do not use sticker and isolated fire at restrictor elbow | YES |
| 2 | gas pipework exits the meter through the top of the meter box | issued warning notice, applied a do not use sticker, the tenant declined isolation      | YES |
| 3 |                                                               |                                                                                         |     |
| 4 |                                                               |                                                                                         |     |
| 5 |                                                               |                                                                                         |     |

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

NO

Number of Appliances Tested:

3

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON OR BEFORE:

Tue-05-Nov-2024

Installation Pass:

NO

CO Alarm fitted & working?

NO

Smoke alarm fitted & working?

YES

## Signatures

Report Issued By:

Name: Andrew King-Page

Signed:

Date: Tue-17-Oct-2023

Report Received By:

Name:

Signed:

Date: Tue-17-Oct-2023

Gas ID Number: 5545563