



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.
This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

6 Borrowell Terrace

Certificate No: 6 Borrowell Terrace

Engineers Details

Trading Title
Coventry Gas Services Ltd

Address
47 Alspath Road
Meriden

Post Code: CV7 7LU

Gas Safe No: 927997

Telephone No: 07961768920

Installation Details

Installation Address
6 Borrowell Terrace ☐ Kenilworth ☐ CV8 1ER
6 Borrowell Terrace ☐ Kenilworth ☐ CV8 1ER
6 Borrowell Terrace ☐ Kenilworth ☐ CV8 1ER
6 Borrowell Terrace ☐ Kenilworth ☐ CV8 1ER

Post Code:

Client Details

Client Address
Mr S Worrall
C/o Leaders
1 Warwick Road
Kenilworth

Post Code: CV8 1HD

Telephone No:

Telephone No:

Appliance Details

Inspection Details

	Location	Appliance Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	Flue Type (OF/RS/FL)	Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure (mbar) or Heat Input (kW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Kitchen	Combi Boiler	Vaillant	S 831 VUW 316/3-5 VUW	9.0	45	RS	YES	0.0005	YES	27.34 kw	YES	YES	YES	N/A	NO	YES
2	Kitchen	Hob	Ikea	Mojliq	NA	NA	FL	YES	NA	YES	19 kw	YES	YES	NA	N/A	NO	YES
3	Lounge	Fire	Unknown	Unknown	NA	NA	OF	YES	NA	YES	NA mb	NO	NO	YES	FAIL	NO	NO
4																	
5																	

Faults/Notes

Remedial Work Taken

Warning Notice Fixed

1	gas fire has been capped off previous to visit	advised landlord	NO
2	no ep bonding on meter	advised landlord	NO
3			
4			
5			

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

YES

Number of Appliances Tested:

3

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON OR BEFORE:

Sun-29-Sept-2024

Installation Pass:

YES

CO Alarm fitted & working?

YES

Smoke alarm fitted & working?

YES

Signatures

Report Issued By:

Name: Andrew King-Page

Signed:

Date: Tue-19-Sept-2023

Report Received By:

Name:

Signed:

Date: Tue-19-Sept-2023

Gas ID Number: 5545563