



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

44 Glendon Road Erdington
Birmingham B23 5HG

Certificate No: 44 Glendon Road
Erdington Birmingham B23
5HG

Engineers Details

Trading Title Coventry Gas Ltd

Address 47 Alspath Road
Meriden

Post Code: CV7 7LU

Gas Safe No: 526645

Telephone No: 07961768920

Installation Details

Installation Address

44 Glendon Road Erdington Birmingham B23 5HG
44 Glendon Road Erdington Birmingham B23 5HG
44 Glendon Road Erdington Birmingham B23 5HG
44 Glendon Road Erdington Birmingham B23 5HG

Post Code:

Client Details

Client Address

Bal Forwell
44 Glendon Road
Birmingham
West Midlands

Post Code: B23 5HG

Telephone No:

Telephone No:

07703819955

Appliance Details

Inspection Details

	Location	Appliance Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	Flue Type (OF/RS/FL)	Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(kW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Lounge	Fire	Royal	super ferrona 16 mk2	NA	NA	OF	YES	NA	YES	NA mb	NO	YES	YES	N/A	NO	NO
2	Kitchen	Hob	Moffat	Unknown	NA	NA	FL	YES	NA	YES	18 mb	YES	YES	NA	N/A	NO	YES
3	Airing Cupboard	Combi Boiler	Glow worm	Compact 24c	9.4	47	RS	YES	0.0005	YES	23.49 kw	YES	YES	YES	N/A	YES	YES
4																	
5																	

Faults/Notes

Remedial Work Taken

Warning Notice Fixed

1	gas fire had been disconnected prior to inspection	none	NO
2			
3			
4			
5			

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

YES

Number of Appliances Tested:

3

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON OR BEFORE:

Fri-16-Feb-2024

Installation Pass:

YES

CO Alarm fitted & working?

YES

Smoke alarm fitted & working?

YES

Signatures

Report Issued By:

Name: Andrew King-Page

Signed:

Date: Thu-16-Feb-2023

Report Received By:

Name:

Signed:

Date: Thu-16-Feb-2023

Gas ID Number: 4464997