



# Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

40 Quarry Street Leamington Spa  
Warwickshire CV32 6AU

Certificate No: 40 Quarry Street  
Leamington Spa  
Warwickshire CV32 6AU

## Engineers Details

Trading Title: Coventry Gas Ltd  
Address: 47 Alspath Road  
Meriden  
Post Code: CV7 7LU

Gas Safe No: 526645 Telephone No: 07961768920

## Installation Details

Installation Address: works order LSP22000149  
40 Quarry Street  
Leamington Spa  
Warwickshire  
Post Code: CV32 6AU

Telephone No:

## Client Details

Client Address: Mr George Tucker c/o Reeds Rains Ltd  
34/35 Denby Buildings  
Regent Grove  
Leamington Spa  
Post Code: CV32 4NY

Telephone No: 01926 311431

## Appliance Details

## Inspection Details

|   | Location | Appliance Type | Make     | Model           | CO2 Reading (%) | CO Reading (ppm) | Flue Type (OF/RS/FL) | Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only) | Combustion Analysis Reading (CO/CO2) | Landlords Appliance (YES/NO/NA) | Operating Pressure (mbar) or Heat Input (kW) | Safety Device(s) Correct Operation (YES/NO/NA) | Ventilation Provision Satisfactory (YES/NO) | Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA) | Flue Performance Test (PASS/FAIL/NA) | Appliance Serviced (YES/NO/NA) | Appliance Safe To Use (YES/NO) |
|---|----------|----------------|----------|-----------------|-----------------|------------------|----------------------|------------------------------------------------------------------|--------------------------------------|---------------------------------|----------------------------------------------|------------------------------------------------|---------------------------------------------|-------------------------------------------------------------------|--------------------------------------|--------------------------------|--------------------------------|
| 1 | Kitchen  | Hob            | Lamona   | Unknown         | NA              | NA               | FL                   | YES                                                              | NA                                   | YES                             | 18 mb                                        | YES                                            | YES                                         | NA                                                                | N/A                                  | NO                             | YES                            |
| 2 | Kitchen  | Combi Boiler   | Vaillant | Ecotec Plus 832 | 8.4             | 42               | RS                   | YES                                                              | 0.0005                               | YES                             | 23.54 kw                                     | YES                                            | YES                                         | YES                                                               | N/A                                  | NO                             | YES                            |
| 3 |          |                |          |                 |                 |                  |                      |                                                                  |                                      |                                 |                                              |                                                |                                             |                                                                   |                                      |                                |                                |
| 4 |          |                |          |                 |                 |                  |                      |                                                                  |                                      |                                 |                                              |                                                |                                             |                                                                   |                                      |                                |                                |
| 5 |          |                |          |                 |                 |                  |                      |                                                                  |                                      |                                 |                                              |                                                |                                             |                                                                   |                                      |                                |                                |

## Faults/Notes

## Remedial Work Taken

## Warning Notice Fixed

|   |                                           |                  |    |
|---|-------------------------------------------|------------------|----|
| 1 | boiler requires a full strip down service | advised landlord | NO |
| 2 |                                           |                  |    |
| 3 |                                           |                  |    |
| 4 |                                           |                  |    |
| 5 |                                           |                  |    |

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

YES

Number of Appliances Tested:

2

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON OR BEFORE:

Fri-24-Nov-2023

Installation Pass:

YES

CO Alarm fitted & working?

YES

Smoke alarm fitted & working?

YES

## Signatures

Report Issued By:

Name: Andrew King-Page

Signed:

Date: Thu-24-Nov-2022

Report Received By:

Name:

Signed:

Date: Thu-24-Nov-2022

Gas ID Number: 4464997