



# Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

363 Lentons Lane Gs

Certificate No: 363 Lentons Lane

## Engineers Details

Trading Title Coventry Gas Ltd

Address 47 Alspath Road  
Meriden  
Meriden

Post Code: CV7 7LU

Gas Safe No: 526645

Telephone No: 07502848685

## Installation Details

Installation Address

363 Lentons Lane  
Coventry

Post Code: CV2 1AA

## Client Details

Client Address

H2L Lettings  
38 Main Road  
Meriden

Post Code: CV7 7NF

## Appliance Details

## Inspection Details

|   | Location      | Appliance Type | Make | Model     | CO2 Reading (%) | CO Reading (ppm) | Flue Type (OF/RS/FL) | Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only) | Combustion Analysis Reading (CO/CO2) | Landlords Appliance (YES/NO/NA) | Operating Pressure(mbar) or Heat Input(kW) | Safety Device(s) Correct Operation (YES/NO/NA) | Ventilation Provision Satisfactory (YES/NO) | Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA) | Flue Performance Test (PASS/FAIL/NA) | Appliance Serviced (YES/NO/NA) | Appliance Safe To Use (YES/NO) |
|---|---------------|----------------|------|-----------|-----------------|------------------|----------------------|------------------------------------------------------------------|--------------------------------------|---------------------------------|--------------------------------------------|------------------------------------------------|---------------------------------------------|-------------------------------------------------------------------|--------------------------------------|--------------------------------|--------------------------------|
| 1 | Downstairs Wc | Combi Boiler   | Baxi | 424 Combi | 9.0             | 69               | RS                   | YES                                                              | 0.0008                               | YES                             | 24.39 kw                                   | YES                                            | YES                                         | YES                                                               | PASS                                 | YES                            | YES                            |
| 2 |               |                |      |           |                 |                  |                      |                                                                  |                                      |                                 |                                            |                                                |                                             |                                                                   |                                      |                                |                                |
| 3 |               |                |      |           |                 |                  |                      |                                                                  |                                      |                                 |                                            |                                                |                                             |                                                                   |                                      |                                |                                |
| 4 |               |                |      |           |                 |                  |                      |                                                                  |                                      |                                 |                                            |                                                |                                             |                                                                   |                                      |                                |                                |
| 5 |               |                |      |           |                 |                  |                      |                                                                  |                                      |                                 |                                            |                                                |                                             |                                                                   |                                      |                                |                                |

## Faults/Notes

## Remedial Work Taken

## Warning Notice Fixed

|   |                                  |                                 |    |
|---|----------------------------------|---------------------------------|----|
| 1 | PRV connection to boiler weeping | Advised landlord to be repaired | NA |
| 2 |                                  |                                 |    |
| 3 |                                  |                                 |    |
| 4 |                                  |                                 |    |
| 5 |                                  |                                 |    |

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

YES

Number of Appliances Tested:

1

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON OR BEFORE:

Fri-16-Jun-2023

Installation Pass:

YES

CO Alarm fitted & working?

YES

Smoke alarm fitted & working?

YES

## Signatures

Report Issued By:

Name: Steve Owen

Signed: \_\_\_\_\_

Gas ID Number: Na

Date: Thu-16-Jun-2022

Report Received By:

Name: \_\_\_\_\_

Signed: *C. Hays*

Date: Thu-16-Jun-2022