



# Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

18 Triumph Close-G2M  
Group-18May2022

Certificate No: 18 Triumph Close Gs

## Engineers Details

Trading Title: Coventry Gas Ltd  
Address: 47 Alspath Road, Meriden, Meriden  
Post Code: CV7 7LU  
Gas Safe No: 526645  
Telephone No: 07502848685

## Installation Details

Installation Address: Mr Merson Siddall, 18 Triumph Colse, Coventry  
Post Code: CV2 5AQ  
Telephone No:

## Client Details

Client Address: G2M Group, 25 Jetstream Drive, Auckley, Doncaster  
Post Code: DN9 3QS  
Telephone No: 01302 230579

## Appliance Details

## Inspection Details

|   | Location | Appliance Type | Make      | Model           | CO2 Reading (%) | CO Reading (ppm) | Flue Type (OF/RS/FL) | Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only) | Combustion Analysis Reading (CO/CO2) | Landlords Appliance (YES/NO/NA) | Operating Pressure(mbar) or Heat Input(kW) | Safety Device(s) Correct Operation (YES/NO/NA) | Ventilation Provision Satisfactory (YES/NO) | Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA) | Flue Performance Test (PASS/FAIL/NA) | Appliance Serviced (YES/NO/NA) | Appliance Safe To Use (YES/NO) |
|---|----------|----------------|-----------|-----------------|-----------------|------------------|----------------------|------------------------------------------------------------------|--------------------------------------|---------------------------------|--------------------------------------------|------------------------------------------------|---------------------------------------------|-------------------------------------------------------------------|--------------------------------------|--------------------------------|--------------------------------|
| 1 | Bed Room | Combi Boiler   | Worcester | Greenstar 25 Si | 9.2             | 65               | RS                   | NO                                                               | 0.0007                               | YES                             | 25.32 kw                                   | YES                                            | YES                                         | YES                                                               | PASS                                 | NO                             | YES                            |
| 2 | Kitchen  | Hob            | Lamona    |                 | NA              | NA               | N/A                  | YES                                                              | NA                                   | YES                             | 19 mb                                      | YES                                            | NA                                          | NA                                                                | N/A                                  | NO                             | YES                            |
| 3 |          |                |           |                 |                 |                  |                      |                                                                  |                                      |                                 |                                            |                                                |                                             |                                                                   |                                      |                                |                                |
| 4 |          |                |           |                 |                 |                  |                      |                                                                  |                                      |                                 |                                            |                                                |                                             |                                                                   |                                      |                                |                                |
| 5 |          |                |           |                 |                 |                  |                      |                                                                  |                                      |                                 |                                            |                                                |                                             |                                                                   |                                      |                                |                                |

## Faults/Notes

## Remedial Work Taken

## Warning Notice Fixed

|   |  |  |
|---|--|--|
| 1 |  |  |
| 2 |  |  |
| 3 |  |  |
| 4 |  |  |
| 5 |  |  |

Emergency Control Valve Accessible: YES  
Gas Tightness Satisfactory: NA  
Gas Installation Pipework Visual Inspection Satisfactory: YES  
Number of Appliances Tested: 1  
Equipotential Bonding: YES  
NEXT INSPECTION DUE ON OR BEFORE: Sun-18-Jun-2023  
Installation Pass: YES  
CO Alarm fitted & working? YES  
Smoke alarm fitted & working? YES

## Signatures

Report Issued By:

Name: Steve Owen

Signed: \_\_\_\_\_

Gas ID Number: Na

Date: Wed-18-May-2022

Report Received By:

Name: \_\_\_\_\_

Signed: \_\_\_\_\_

Date: Wed-18-May-2022